

Errata

XMSM0C110x, XMS003Fx Microcontrollers



ABSTRACT

This document describes the known exceptions to the functional specifications (advisories).

Table of Contents

1 Functional Advisories.....	1
2 Preprogrammed Software Advisories.....	1
3 Debug Only Advisories.....	1
4 Fixed by Compiler Advisories.....	1
5 Device Nomenclature.....	1
5.1 Device Symbolization and Revision Identification.....	2
6 Advisory Descriptions.....	3
7 Revision History.....	5

1 Functional Advisories

Advisories that affect the device's operation, function, or parametrics.

✓ The check mark indicates that the issue is present in the specified revision.

Errata Number	Rev A
ADC_ERR_04	✓
ADC_ERR_05	✓
PMCU_ERR_04	✓
PMCU_ERR_05	✓
PMCU_ERR_06	✓
UART_ERR_01	✓

2 Preprogrammed Software Advisories

Advisories that affect factory-programmed software.

✓ The check mark indicates that the issue is present in the specified revision.

3 Debug Only Advisories

Advisories that affect only debug operation.

✓ The check mark indicates that the issue is present in the specified revision.

4 Fixed by Compiler Advisories

Advisories that are resolved by compiler workaround. Refer to each advisory for the IDE and compiler versions with a workaround.

✓ The check mark indicates that the issue is present in the specified revision.

5 Device Nomenclature

To designate the stages in the product development cycle, TI assigns prefixes to the part numbers of all MSP MCU devices. Each MSP MCU commercial family member has one of two prefixes: MSP or XMS. These

prefixes represent evolutionary stages of product development from engineering prototypes (XMS) through fully qualified production devices (MSP).

XMS – Experimental device that is not necessarily representative of the final device's electrical specifications

MSP – Fully qualified production device

Support tool naming prefixes:

X: Development-support product that has not yet completed Texas Instruments internal qualification testing.

null: Fully-qualified development-support product.

XMS devices and X development-support tools are shipped against the following disclaimer:

"Developmental product is intended for internal evaluation purposes."


MSP devices have been characterized fully, and the quality and reliability of the device have been demonstrated fully. TI's standard warranty applies.

Predictions show that prototype devices (XMS) have a greater failure rate than the standard production devices. TI recommends that these devices not be used in any production system because their expected end-use failure rate still is undefined. Only qualified production devices are to be used.

TI device nomenclature also includes a suffix with the device family name. This suffix indicates the temperature range, package type, and distribution format.

5.1 Device Symbolization and Revision Identification

The package diagrams below indicate the package symbolization scheme, and [Table 5-1](#) defines the device revision to version ID mapping.



YM = Year, month date code
S = Assembly site
= Die revision
LLLL = Assembly lot code

Figure 5-1. Package Symbolization

Table 5-1. Die Revisions

Revision Letter (package marking)	Version (in the device factory constants memory)
A	1

The revision letter indicates the product hardware revision. Advisories in this document are marked as applicable or not applicable for a given device based on the revision letter. This letter maps to an integer stored in the memory of the device, which can be used to look up the revision using application software or a connected debug probe.

6 Advisory Descriptions

ADC_ERR_04 *The trim of ADC offset error is not correctly applied*

Revisions Affected

Rev A

Details

The value of ADC offset error trim is not correctly applied. As a result, the offset can be in the range of +/-10mV.

This issue is going to be resolved in next version.

Workaround

Implement the user's own calibration and compensating the offset during the ADC measurement.

ADC_ERR_05 *ADC 10-bit DNL performance exceeds -1LSB*

Revisions Affected

Rev A

Details

When the ADC is configured as 10-bit resolution, the DNL performance could hit the targeted specification of -1LSB.

This issue is going to be resolved in next version.

Workaround

N/A

PMCU_ERR_04 *nRST pin low for more than 1 second does not trigger POR*

Revisions Affected

Rev A

Details

Applying a low signal to the nRST pin for more than 1 second does not trigger POR, instead, it results a BOOTRST.

This issue is going to be resolved in next version.

Workaround

Considering BOOTRST to reset the device instead of POR.

PMCU_ERR_05 ***SRAM and internal LDO generate high leakage current***

Revisions Affected Rev A

Details

Due to the timing issue caused by the internal logic, when the operating temperature is over 105C, SRAM and internal LDO have high leakage current. This prevents the device from entering STANDBY0 or STANDBY1 mode.

This issue is going to be resolved in next version.

Workaround

Limit the operating temperature to be <105C.

PMCU_ERR_06 ***CPU AND DMA are not able to access the flash at the same time***

Revisions Affected Rev A

Details

CPU AND DMA cannot concurrently access the flash; for instance, this simultaneous access results in reading incorrect data from the flash during the flash erase operation.

This issue is going to be resolved in next version.

Workaround

Do not access the flash via CPU AND DMA concurrently.

UART_ERR_01 *UART is failed to request asynchronous fast clock in STANDBY1 mode*

Revisions Affected Rev A

Details

When the device is operating STANDBY1 mode, it can be awakened by UART transmission (start condition) and request an asynchronous fast clock. After that, it re-enters STANDBY1 mode. If a new start condition in UART communication occurs during the transition to STANDBY1 mode, the UART is not able to detect it and request an asynchronous fast clock.

Workaround

Use STANDBY0 or higher power mode when UART is needed to detect the new start conduction.

7 Revision History

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

DATE	REVISION	NOTES
October 2023	*	Initial Release

IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATA SHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, regulatory or other requirements.

These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to [TI's Terms of Sale](#) or other applicable terms available either on [ti.com](#) or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products.

TI objects to and rejects any additional or different terms you may have proposed.

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265
Copyright © 2023, Texas Instruments Incorporated