

Errata Report for the UCD90120 and UCD90124 Devices

1 PWM1 and PWM2 can not get set to 0% duty cycle (UCD90120 and UCD90124)

Problem Description: When either PWM1 or PWM2 (pins 31 and 32 respectively) are configured as PWM outputs and are set with duty cycle of 0%, then a small glitch occurs on that signal.



Figure 1. Capture of glitch at PWM1 set to 0% duty cycle

Suggested Workaround: If a glitch is not acceptable for a 0% setting of the duty cycle, then select from the other PWM pins available (PWM 3-4, FPWM 1-8).

2 PWM1 and PWM2 can not get set to 0% duty cycle with immediate speed updates set when controlling fans (UCD90124)

Problem Description: When the fan gets a new speed setting (manually or automatically adjusted), the percentage change in speed per second can be set in the FAN_CONFIG parameter "Speed change". For PWM1 or PWM2, if the fan is set for immediate speed updates and the fan is changed from any non-zero duty cycle setting to 0%, then the fan will stay at the non-zero duty cycle. If the fan was not set for immediate speed updates and the fan speed is changed from non-zero duty cycle to 0%, then the fan speed will walk down to 1% and stay there.

Suggested Workaround: If immediate speed update is desired then select the maximum speed update setting (8% per second) or select 1% as the desired end target duty cycle. Setting 1% in lieu of 0% for fan control is usually acceptable because most fans require a minimum duty cycle for them to operate.

3 Must configure FPWMs after PWMs (UCD90120 and UCD90124)

Problem Description: Configuring a PWM (pins 31, 32, 41 and 42) after a FPWM (pins 17-24) will corrupt the frequency setting for the FPWM. This problem is only observed when making direct I²C/PMBus commands to reconfigure the PWM/FPWM pins.

Suggested Workaround: When using the PWM_CONFIG command, configure all PWMs before configuring any FPWMs.

4 Setting phase of 360° for FPWMs shuts down the FPWM (UCD90120 and UCD90124)

Problem Description: Setting the phase of an FPWM (pins 17-24) to 360° turns off the FPWM signal, forcing a 0V output.

Suggested Workaround: If setting the phase to 360° is required, then use 0° instead. Technically a phase of 0° is the same as a phase of 360°.

5 LOGGED_FAULT_DETAIL_INDEX can become invalid when using FIFO modes (UCD90120 and UCD90124)

Problem Description: If the LOGGED_FAULT_DETAIL is configured for one of the two FIFO modes, the LOGGED_FAULT_DETAIL_INDEX will be invalid after rollover and a reset. The "Total Number of LOGGED_FAULT_DETAIL entries" should be equal to the maximum number of LOGGED_FAULT_DETAIL entries. Instead, it is equal to the number of new entries since the rollover.

Example 1:

1. The maximum fault detail entries is 10
2. The log is configured as a **full FIFO**
3. 12 faults are logged
4. The device is reset

The device reports that there are 2 log detail entries

Example 2:

1. The maximum fault detail entries is 10
2. The log is configured as a **half FIFO**
3. 12 faults are logged
4. The device is reset

The device reports that there are 7 log detail entries

In both cases, there are actually 10 valid log entries, but the device will not let you read past the number of entries that it reports.

Suggested Workaround: The log detail FIFO modes should not be used. Ensure that FIFO mode is disabled in the Miscellaneous Configuration Byte within the MISC_CONFIG command.

6 CLEAR_FAULTS command does not clear "Sequencing Timeout" and "Slaved Fault" bits (UCD90120 and UCD90124)

Problem Description: The CLEAR_FAULTS command does not clear the "Sequencing Timeout" and "Slaved Fault" status bits that are in the MFR_STATUS command for every rail.

Suggested Workaround: These bits get cleared when the associated rail is re-enabled.

7 Fan System Shutdown and fan Fault Increase Speed can't be used at the same time (UCD90124)

Problem Description: The fan System Shutdown Enable and the fan Fault Increase Speed that are set within the FAN_CONFIG command can not be used at the same time.

Suggested Workaround: Do not enable the fan System Shutdown Enable and the Fault Increase Speed at the same time.

8 Reading the GPIO_CONFIG for certain pins can change the state of the pin (UCD90120 and UCD90124)

Problem Description: Reading the GPIO_CONFIG for certain pins can change the state of the pin.

Suggested Workaround: Limit the use of GPIO_CONFIG command to only writes.

9 Using the Boolean Logic, GPOs defaulted to true show short glitch on GPO after a reset (UCD90120/UCD90124)

Problem Description: Any time that you have a GPO configured to a logic equation in which the default state is true when the device comes out of RESET, you will see a short glitch on the GPO. On a reset, the device initializes the GPOs to “false”, so if the condition is really supposed to be initialized to true, there will be a glitch.

Suggested Workaround: If a glitch is not acceptable on the GPO then may be able to add a filter on the GPO that would remove the glitch.

10 Command to Turn On rail ignored during a delayed Turn Off (UCD90120 and UCD90124)

Problem Description: When a rail is in the process of turning off with delay, it will ignore any command given to turn back on.

Suggested Workaround: Must ensure that turn on commands are given after the turn off delay has expired and the rail has actually turned off. If the commands were sent before the delay expires then the command should be resent once the delay expires.

11 Cautionary Use of PWM for Power Supply Margining (UCD90120 and UCD90124)

Problem Description: The UCD90120 and UCD90124 have two types of PWMs – Fast Pulsed Width Modulators (FPWM1–FPWM8) and generic PWMs (PWM1–PWM4). The product datasheet gives indication that all PWM types can be used for power supply margining.

It should be noted with this errata that caution must be taken when using PWM1–PWM4 for margining. Margining with a PWM seems to be acceptable when the appropriate external components are selected (per the application). While using any of PWM1–PWM4, a glitch may occur when the duty cycle is updated. This causes the rail output voltage to decrease below its permitted low voltage thresholds momentarily, and then go back to the desired margining setpoint. By selecting proper filter capacitor, that voltage dip can be reduced to ~2% below the setpoint.

Suggested Workaround: Although this might not be an issue for all applications, it is recommended that PWM1–PWM4 are not used for power supply margining. Using PWM1–PWM4 for margining is under application system designer’s discretion after evaluating actual operation in their system and determining that it is not an issue.

All FPWMs (FPWM1–FPWM8) operate as expected for power supply margining.

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of TI information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation. Information of third parties may be subject to additional restrictions.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

TI products are not authorized for use in safety-critical applications (such as life support) where a failure of the TI product would reasonably be expected to cause severe personal injury or death, unless officers of the parties have executed an agreement specifically governing such use. Buyers represent that they have all necessary expertise in the safety and regulatory ramifications of their applications, and acknowledge and agree that they are solely responsible for all legal, regulatory and safety-related requirements concerning their products and any use of TI products in such safety-critical applications, notwithstanding any applications-related information or support that may be provided by TI. Further, Buyers must fully indemnify TI and its representatives against any damages arising out of the use of TI products in such safety-critical applications.

TI products are neither designed nor intended for use in military/aerospace applications or environments unless the TI products are specifically designated by TI as military-grade or "enhanced plastic." Only products designated by TI as military-grade meet military specifications. Buyers acknowledge and agree that any such use of TI products which TI has not designated as military-grade is solely at the Buyer's risk, and that they are solely responsible for compliance with all legal and regulatory requirements in connection with such use.

TI products are neither designed nor intended for use in automotive applications or environments unless the specific TI products are designated by TI as compliant with ISO/TS 16949 requirements. Buyers acknowledge and agree that, if they use any non-designated products in automotive applications, TI will not be responsible for any failure to meet such requirements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

Products		Applications	
Amplifiers	amplifier.ti.com	Audio	www.ti.com/audio
Data Converters	dataconverter.ti.com	Automotive	www.ti.com/automotive
DLP® Products	www.dlp.com	Communications and Telecom	www.ti.com/communications
DSP	dsp.ti.com	Computers and Peripherals	www.ti.com/computers
Clocks and Timers	www.ti.com/clocks	Consumer Electronics	www.ti.com/consumer-apps
Interface	interface.ti.com	Energy	www.ti.com/energy
Logic	logic.ti.com	Industrial	www.ti.com/industrial
Power Mgmt	power.ti.com	Medical	www.ti.com/medical
Microcontrollers	microcontroller.ti.com	Security	www.ti.com/security
RFID	www.ti-rfid.com	Space, Avionics & Defense	www.ti.com/space-avionics-defense
RF/IF and ZigBee® Solutions	www.ti.com/lprf	Video and Imaging	www.ti.com/video
		Wireless	www.ti.com/wireless-apps

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265
Copyright © 2010, Texas Instruments Incorporated