



ABSTRACT

This document describes the known exceptions to the functional specifications (advisories).

Table of Contents

1 Functional Advisories	1
2 Preprogrammed Software Advisories	2
3 Debug Only Advisories	2
4 Fixed by Compiler Advisories	2
5 Device Nomenclature	2
5.1 Device Symbolization and Revision Identification.....	2
6 Advisory Descriptions	4
7 Trademarks	13
8 Revision History	13

1 Functional Advisories

Advisories that affect the device operation, function, or parametrics.

✓ The check mark indicates that the issue is present in the specified revision.

Errata Number	Rev A
AES_ERR_01	✓
CPU_ERR_05	✓
GSC_ERR_01	✓
IOMUX_ERR_01	✓
I2S_ERR_01	✓
KEYSTORE_ERR_01	✓
PMCU_ERR_15	✓
SYSCTL_ERR_01	✓
SYSPLL_ERR_01	✓
TIMER_ERR_04	✓
TIMER_ERR_06	✓
TIMER_ERR_07	✓
TIMER_ERR_08	✓
UNICOMMI2CC_ERR_01	✓
UNICOMMI2CC_ERR_02	✓
UNICOMMUART_ERR_01	✓
UNICOMMUART_ERR_03	✓
UNICOMMUART_ERR_04	✓
UNICOMMUART_ERR_05	✓
UNICOMMUART_ERR_06	✓
UNICOMMUART_ERR_07	✓

Errata Number	Rev A
UNICOMMUART_ERR_10	✓

2 Preprogrammed Software Advisories

Advisories that affect factory-programmed software.

✓ The check mark indicates that the issue is present in the specified revision.

3 Debug Only Advisories

Advisories that affect only debug operation.

✓ The check mark indicates that the issue is present in the specified revision.

4 Fixed by Compiler Advisories

Advisories that are resolved by compiler workaround. Refer to each advisory for the IDE and compiler versions with a workaround.

✓ The check mark indicates that the issue is present in the specified revision.

5 Device Nomenclature

To designate the stages in the product development cycle, TI assigns prefixes to the part numbers of all MSP MCU devices. Each MSP MCU commercial family member has one of two prefixes: MSP or XMS. These prefixes represent evolutionary stages of product development from engineering prototypes (XMS) through fully qualified production devices (MSP).

XMS – Experimental device that is not necessarily representative of the final device's electrical specifications

MSP – Fully qualified production device

Support tool naming prefixes:

X: Development-support product that has not yet completed Texas Instruments internal qualification testing.

null: Fully-qualified development-support product.

XMS devices and X development-support tools are shipped against the following disclaimer:

"Developmental product is intended for internal evaluation purposes."

MSP devices have been characterized fully, and the quality and reliability of the device have been demonstrated fully. TI's standard warranty applies.

Predictions show that prototype devices (XMS) have a greater failure rate than the standard production devices. TI recommends that these devices not be used in any production system because their expected end-use failure rate still is undefined. Only qualified production devices are to be used.

TI device nomenclature also includes a suffix with the device family name. This suffix indicates the temperature range, package type, and distribution format.

5.1 Device Symbolization and Revision Identification

The package diagrams below indicate the package symbolization scheme, and [Table 5-1](#) defines the device revision to version ID mapping.




Figure 5-1. Package Symbolization

Table 5-1. Die Revisions

Revision Letter	Version (in the device factory constants memory)
A	0

The revision letter indicates the product hardware revision. Advisories in this document are marked as applicable or not applicable for a given device based on the revision letter. This letter maps to an integer stored in the memory of the device, which can be used to look up the revision using application software or a connected debug probe.

6 Advisory Descriptions

AES_ERR_01

AES Module

Category

Functional

Function

AES Saved Context Ready interrupt is not generating as expected

Description

Saved Context Ready interrupt is not getting generated. The interrupt is generated if an access (read or write) is made to any AES register.

Workaround

Use polling based mechanism to check the status bit for Saved Context Ready in CTRL register instead of interrupt.

CPU_ERR_05

CPU Module

Category

Functional

Function

MTB_BASE register value gets read improperly

Description

When Reading the MTB_BASE register the MTB_SRAM base location will be right shifted by a bit. For example, if the MTB_SRAM shows 0x80806000 the actual MTB_SRAM base location is 0x40403000.

Workaround

When reading the MTB_BASE register to find the MTB_SRAM base location right shift the read value by one bit. Please use the code below to work around the issue: `uint32_t mtb_base = (*(uint32_t*)(0xE004300C) >> 1);`

GSC_ERR_01

GSC Module

Category

Functional

Function

Certain timers have the same security attribute

Description

In the PPC_SECATTRIB_TIMER register the SEC_TIMA0_0 and SEC_TIMA0_1 registers are tied together such that the security attribute for both TIMERA0_0 and TIMERA0_1 must be the same. TIMERG4_2 and TIMERG4_1 also have the same configuration but only when the DMA is attempting to access the timers.

Workaround

Try to keep both TIMERA0_0 and TIMERA0_1 as the same security level. If that's not possible use a different pair of timer instances. For TIMERG4_2 and TIMERG4_1 keep them at the same security level especially if using a DMA to access the TIMERG4_2 or TIMERG4_1.

IOMUX_ERR_01 ***IOMUX Module***

Category Functional

Function TDO pin drives a low signal after reset.

Description The TDO pin out of reset is driven as a low signal. For other pins they are in a Hi-Z state out of reset.

Workaround If you need this pin to be a Hi-Z state set both the PC and PF bits to zero. Otherwise connect the peripheral you plan to use on this IO.

I2S_ERR_01 ***I2S Module***

Category Functional

Function The first TXIFG interrupt does not get fired after I2S/TDM module enabled

Description Upon I2S/TDM module enable, the first TXIFG interrupt does not get fired.

Workaround Write a 1 to the INTCTL.INTEVAL bit to generate the initial TXIFG interrupt.

KEYSTORE_ERR_01 ***KEYSTORE Module***

Category Functional

Function STATUS.STAT value can be 0 or 1 without key access

Description STATUS.STAT has a reset value of 1 and turns to 0 under these conditions: 1. After reset, debugger access via the register window returns 0x00. 2. After reset, the first CPU read returns 0x01, while subsequent CPU reads return 0x00. 3) After reset, first reading any other KEYSTORE register and then reading STATUS.STAT return 0x00.

Workaround STATUS.STAT=0x0 means "No Error" . For checking if a slot is valid or not (Whether key is present), check STATUS.VALID.

PMCU_ERR_15 ***PMCU Module***

Category Functional

Function GENCLKEN Clock related configurations before SYSPLL is enabled are ignored

PMCU_ERR_15

(continued)

PMCU Module

Description

When configuring the SYSPLL, configure the GENCLKEN register after setting the SYSPLLEN bit in the HSCLKEN register. If the EXTDIVCAN, MCLKEXTDIVEN and I2SPLLCLKDIVEN, I2SPLLCLKDIVCFG bits in the GENCLKEN register are programmed before the SYSPLLEN bit is set, the configuration in the GENCLKEN register is not properly configured and the EXTDIVCAN and I2SPLLCLKDIVCFG configurations are ignored.

Workaround

Configure the EXTDIVCAN, MCLKEXTDIVEN and I2SPLLCLKDIVEN, I2SPLLCLKDIVCFG bits in the GENCLKEN registers, after the SYSPLLEN bit is set.

SYSCTL_ERR_01 **SYSCTL Module**

Category

Functional

Function

SW-POR functionality is combined with HW-POR

Description

When a user writes to the LFSSRST register with the correct key to generate a software-triggered POR, the RSTCAUSE register will display 0x2 (indicating an NRST-triggered POR) instead of the expected 0x3 (Software-Triggered POR). This occurs because the SW-POR functionality is combined with the HW-POR path.

Workaround

No

SYSPLL_ERR_01 **SYSPLL Module**

Category

Functional

Function

SYSPLL Frequency may not lock to correct frequency when enabled.

Description

When setting the SYSPLLEN bit to 1 in SYSCTL HSCLKEN register, the SYSPLL will run the phase locked loop search. The search can potentially fail where the frequency will not be set to the correct value, instead the resultant frequency will be drastically different than the configured frequency.

Workaround
Frequency Verification Process

Monitor the SYSPLL frequency output using the Frequency Clock Counter (FCC) whenever the SYSPLLEN bit is set to 1. Once the correct frequency is established, it will remain stable until the SYSPLL is disabled and re-enabled (SYSPLLEN bit toggled from 0 to 1). If an incorrect frequency is detected, disable and re-enable the SYSPLL to perform another verification.

Workaround 1: FCC Count Check

Use LFCLK as the FCC trigger source to count the SYSPLL output clock frequency. Execute the FCC and verify the measured value against the configured SYSPLL

SYSPLL_ERR_01

(continued)

SYSPLL Module

frequency using LFCLK as reference.

Example calculation:

- SYSPLLCLK0 = 160MHz; LFCLK = 32.768kHz
- Measured FCC Count = $160,000,000/32,768 = 4,882$

FCC Count Tolerance:

The real FCC count will vary depending on the combined clock accuracies (SYSPLLCLK0 and LFCLK). Recommend to add +/- 5~10% to allowed FCC check range.

- FCC count upper limit = $4,882 * 1.05 = 5,126$
- FCC count lower limit = $4,882 * 0.95 = 4,638$

Timing considerations:

- Clock synchronization time: 5-6 LFCLK cycles
- FCC trigger time: 1-32 LFCLK cycles (user-configurable)

Register Configuration:

- FCC Settings: SYSCTL.GENCLKCFG.FCCTRIGSRC = 1;
- SYSCTL.GENCLKCFG.FCCLVLRIG = 0;
- SYSCTL.GENCLKCFG.FCCTRIGCNT = 0;
- SYSCTL.GENCLKCFG.FCCSELCLK = 4;
- Start FCC: SYSCTL.FCCCMD = 0x0E000001U
- Check FCC Done Status: SYSCTL.CLKSTATUS.FCCDONE
- Read FCC Count: SYSCTL.FCC

Timeout Protection:

Implement a software-based timeout during FCC Done status monitoring to prevent longer wait time under the condition the unlocked SYSPLL frequency is less than FCC trigger clock frequency (LFCLK).

```
fccTimeOutCounter = 0;
while (DL_SYSCTL_isFCCDone() == 0) {
    delay_cycles(977); /* 1x LFCLK cycle = 32MHz/32.768kHz */
    fccTimeOutCounter++;
    if(fccTimeOutCounter > 65) break;
    /* Timeout set to approximately 2ms (user-customizable) */
}
```

FCC Check Restart:

If the FCC measurement falls outside the expected range, disable and re-enable the SYSPLL (set SYSPLLEN to 0, then 1) and repeat the FCC verification.

Workaround 2: FCC Ratio Check

Use LFCLK as the FCC trigger source to count both SYSPLL output and input clock frequency. Execute the FCC and verify the measured ratio of the FCC check value between output and input clock to the expected ratio.

Example calculation:

- SYSPLL = 160MHz ; HFCLK = 40MHz ; LFCLK = 32.768kHz
- Expect clock ratio = $160\text{MHz}/40\text{MHz} = 4.0000$
- Measured FCC count (SYSPLL) = $160,000,000/32,768 = 4,882$
- Measured FCC count (HFCLK) = $40,000,000/32,768 = 1,220$
- Measured clock ratio = $4,882/1,220 = 4.0016$

FCC Ratio Tolerance:

The FCC ratio method eliminates combined clock accuracy errors and depends only on FCC uncertainty (2 counted clock cycles) and calculation rounding error. This allows for much tighter tolerance ranges compared to FCC count check method, for example +/- 0.3%.

Timing considerations:

SYSPLL_ERR_01

(continued)

SYSPLL Module

- Clock synchronization time: 5-6 LFCLK cycles
- FCC trigger time: 1-32 LFCLK cycles (user-configurable)
- Total time per complete FCC ratio check: 2*(sync time + trigger time)

FCC Ratio Check Flow:

1. Configure FCC for SYSPLL output clock (SYSPLL0 or SYSPLL2X)
2. Start FCC and wait for FCC done (Add Timeout Protection, refer to FCC Count Check)
3. Read FCC check count back
4. Configure FCC for SYSPLL input clock (SYSOSC or HFCLK)
5. Start FCC and wait for FCC done (Add Timeout Protection, refer to FCC Count Check)
6. Read FCC check count back
7. Calculate the FCC check ratio and compared to the expected ratio range
8. If the FCC ratio falls outside the expected range, disable and re-enable the SYSPLL (set SYSPLLEN to 0, then 1) and repeat the FCC ratio verification.

TIMER_ERR_04**TIMER Module**

Category

Functional

Function

TIMER re-enable may be missed if done close to zero event

Description

When using a TIMER in one shot mode, TIMER re-enable may be missed if done close to zero event. The HW update to the timer enable bit will take a single functional clock cycle. For example, if the timer's clock source is 32.768kHz and clock divider of 3, then it will take ~100us to have the enable bit set to 0 properly.

Workaround

Wait 1 functional clock cycle before re-enabling the timer OR the timer can be disabled first before re-enabling.

Disable the counter with CTRCTL.EN = 0, then re-enable with CTRCTL.EN = 1

TIMER_ERR_06**TIMER Module**

Category

Functional

Function

Writing 0 to CLKEN bit does not disable counter

Description

Writing 0 to the Counter Clock Control Register(CCLKCTL) Clock Enable bit(CLKEN) does not stop the timer.

Workaround

Stop the timer by writing 0 to the Counter Control(CTRCTL) Enable(EN) bit.

UNICOMMI2CC_E**RR_01** (continued) *UNICOMMI2CC Module*

MHz(MFCLK), and CPU_CLK of 80 MHz: Software delay = $3 \times 2 \times (80 \text{ MHz} / 4 \text{ MHz}) = 120$ CPU cycles

UNICOMMI2CC_E**RR_02** *UNICOMMI2CC Module***Category**

Functional

Function

RXDONE interrupt is triggered twice when I2C controller ACKOEN bit is enabled

Description

When I2C controller CTR.ACKONE bit is enable, software controls the sending of ACK/NACK by writing CTR.ACK bit 0 or 1. This can be done in the RXDONE interrupt before the stop condition. After writing the CTR.ACK bit, there will be valid ACK/NACK signal on I2C bus, and an additional RXDONE interrupt will be triggered in the subsequent I2C stop status.

Workaround

Disable the RXDONE interrupt before writing CTR.ACK bit, and manually enable it before next transmission.

UNICOMMUART_E**RR_01** *UNICOMMUART Module***Category**

Functional

Function

Data integrity issues in case glitches are introduced in IrDA mode

Description

UNICOMM-UART supports IrDA but has limitations in noisy environments. Due to the lack of a glitch filter, data integrity issues can occur in IrDA mode when glitches appear on the data line. Since IrDA relies on edge detection logic, these glitches are misinterpreted as valid pulses, leading to unexpected data in the FIFO and issues with LTOOUT computation.

Workaround

No

UNICOMMUART_E**RR_03** *UNICOMMUART Module***Category**

Functional

Function

Data Integrity issues with glitch in Manchester mode

Description

Glitches in the Manchester-encoded data stream corrupt the signal's precise edge timing, leading to erroneous received data and data integrity issues.

**UNICOMMUART_E
RR_03** (continued) *UNICOMMUART Module*

Workaround No

**UNICOMMUART_E
RR_04** *UNICOMMUART Module*

Category Functional

Function Data will be missed with glitches during break field and/or sync field in LIN Mode

Description Break Field Scenario (High-Pulse Glitch): During the Break Field period, a negative edge will reset the counter to zero, cause break field detection failure and result in data loss. Sync Field Scenario: A glitch during Sync Field will trigger false LINC0/LINC1 interrupts, reset the counter on Rx-line negative edges, cause sync field validation failure and result in data loss.

Workaround No

**UNICOMMUART_E
RR_05** *UNICOMMUART Module*

Category Functional

Function Issue due to UART Glitch Filter not being present

Description 1.IrDA Mode Data Integrity: Due to the lack of a glitch filter, data integrity issues can occur in IrDA mode when glitches appear on the data line. Since IrDA relies on edge detection logic, these glitches are misinterpreted as valid pulses. 2.Ideline detection: During IDLELINE detection, a signal glitch can disrupt the detection process by resetting the internal idle line counter to zero. This interference prevents the IDLELINE status flag from being properly set, causing the module to fail to recognize a valid idle condition on the communication line. However, if the idle line condition persists without additional glitches after this disruption, the detection mechanism will eventually recover and properly detect the idle state. 3.Manchester Mode Data Integrity: When signal glitches occur during the data sampling period of Manchester-encoded transmissions, the receiver captures incorrect data, leading to misinterpreted bits. These sampling errors result in corrupted data values being stored in the receive buffer, causing data integrity failures in the received message. Glitches occurring outside the sampling window typically do not affect data interpretation. 4.LIN mode sensitivity around BREAK / SYNC field: a.BREAK Field: During LIN communication, if signal glitches occur specifically during clock sampling periods of the BREAK FIELD, the detection mechanism may prematurely terminate. However, the system demonstrates resilience - if the BREAK FIELD condition continues without additional glitches after the disruption, the detection logic will recover and successfully identify the BREAK FIELD. b.SYNC Field: The system exhibits comparable vulnerability during SYNC field calibration, where glitches can interfere with both negative and positive edge (RXNE & RXPE) detection. 5.LTOUT/RTOUT Detection issue with glitches: When signal glitches occur during idle line detection conditions, they temporarily

UNICOMMUART_E**RR_05** (continued) *UNICOMMUART Module*

disrupt the LTOUT/RTOUT timing calculations, and the timeout counters are cleared back to 0. If the line remains free from additional glitches after the disruption, LTOUT/RTOUT conditions are detected after the configured time-period.

Workaround

No workaround is available.

UNICOMMUART_E**RR_06** *UNICOMMUART Module***Category**

Functional

Function

RTOUT/LTOUT computation issues due to STOP bit handling

Description

On the receiver side, the function state machine transitions from STOP bit to IDLE at the middle of the STOP bit. This causes the receive timeout (RTOUT) & line timeout (LTOUT) counter to start counting at the middle of the STOP bit and not at its end. Leading to RTOUT/LTOUT being triggered half a baud-period early. This is especially pronounced for low-baud rates with higher UART functional clock frequency.

Workaround

Add compensation with a half stop bit period to the RTOUT counter.

UNICOMMUART_E**RR_07** *UNICOMMUART Module***Category**

Functional

Function

RTS line does not go HIGH if UART is disabled in RS-232 mode

Description

When UART is disabled, the RTS line fails to return to its idle state (HIGH), remaining stuck at LOW.

Workaround

Use software to enable the internal pull-up resistor and set the RTS line IO to Hiz mode.

UNICOMMUART_E**RR_10** *UNICOMMUART Module***Category**

Functional

Function

LIN Registers CLKDIV Restriction

Description

When CLKDIV value is other than 0, writing into LINC0/1 will not have any effect.

UNICOMMUART_E
RR_10 (continued) *UNICOMMUART Module*

Workaround

To properly configure LIN registers: 1. First set CLKDIV to '0' 2. Update the LINC0/1 register configurations with desired values 3. Restore CLKDIV to its intended operating value

7 Trademarks

All trademarks are the property of their respective owners.

8 Revision History

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

Changes from April 30, 2026 to June 30, 2026 (from Revision A (April 2026) to Revision B (June 2026))

	Page
• I2S_ERR_01 Description was updated.....	5
• I2S_ERR_01 Workaround was updated.....	5
• I2S_ERR_01 Function was updated.....	5

IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATASHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, regulatory or other requirements.

These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you fully indemnify TI and its representatives against any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to [TI's Terms of Sale](#), [TI's General Quality Guidelines](#), or other applicable terms available either on ti.com or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products. Unless TI explicitly designates a product as custom or customer-specified, TI products are standard, catalog, general purpose devices.

TI objects to and rejects any additional or different terms you may propose.

Copyright © 2026, Texas Instruments Incorporated

Last updated 10/2025