

CC2755P20 SimpleLink Wireless MCU Errata



ABSTRACT

This document describes the known exceptions to functional specifications (advisories) of the CC2755P20 SimpleLink™ device.

This document supports the following devices:

- CC2755P207E0WRHAR
-

Table of Contents

1	Advisories Matrix	2
2	Nomenclature, Package Symbolization, and Revision Identification	3
2.1	Device and Development Support—Tool Nomenclature	3
2.2	Devices Supported	3
2.3	Package Symbolization and Revision Identification	3
3	Advisories	4

Trademarks

SimpleLink™ and Texas Instruments™ are trademarks of Texas Instruments.
All trademarks are the property of their respective owners.

1 Advisories Matrix

Table 1-1 lists all advisories, modules affected, and the applicable silicon revisions.

Table 1-1. Advisories Matrix

MODULE	DESCRIPTION	SILICON REVISIONS AFFECTED
		B
ADC	Advisory ADC_08 —ADC BUSY bit not cleared in repeat single, sequence, and repeat sequence conversion modes	Yes
BATMON	Advisory BATMON_01 —Incorrect temperature measurement	Yes
BATMON	Advisory BATMON_02 —Spurious temperature update interrupts from BATMON in standby	Yes
SYS	Advisory SYS_204 —SysTimer may not always generate a compare event when previously programmed with a value	Yes
SYS	Advisory SYS_206 —The RF phase jumps during HFXT amplitude compensation and HFXT amplitude control	Yes
SYS	Advisory SYS_207 —Standby entry may not be gated if the FLTSETTLED bit is read too soon	Yes
UDMA	Advisory UDMA_01 — μ DMA write response to a peripheral's single request can be missed	Yes

2 Nomenclature, Package Symbolization, and Revision Identification

2.1 Device and Development Support—Tool Nomenclature

To designate the stages in the product development cycle, Texas Instruments™ assigns prefixes to the part numbers of all SimpleLink Wireless devices. Each SimpleLink Wireless part number has one of two prefixes: CC or XC. These prefixes represent evolutionary stages of product development from engineering prototypes (XC) through fully qualified production devices (CC).

Device development evolutionary flow:

- XC** Experimental device that is not necessarily representative of the final device's electrical specifications and may not use production assembly flow.
- CC** Production version of the silicon die that is fully qualified.

XC devices are shipped against the following disclaimer:

"Developmental product is intended for internal evaluation purposes."

Production devices have been characterized fully, and the quality and reliability of the device have been demonstrated fully. TI's standard warranty applies.

Predictions show that prototype devices (X) have a greater failure rate than the standard production devices. Texas Instruments recommends that these devices not be used in any production system because their expected end-use failure rate is still undefined. Only qualified production devices are to be used.

2.2 Devices Supported

This document supports the following devices:

- CC2755P207E0WRHAR

2.3 Package Symbolization and Revision Identification

[Package Symbolization](#) and [Table 2-1](#) describe package symbolization and the device revision code.




Figure 2-1. Package Symbolization

Table 2-1. Revision Identification

Device Revision Code	Silicon Revision
B	PG1.1

The device marking includes the part number CC2755x, where x denotes the power level of the device. ##### is the lot trace code. Optionally, 'X' following the TI letters indicates an experimental device. G4 is the environmental classification.

3 Advisories

ADC_08 ***ADC BUSY bit not cleared in repeat single, sequence, and repeat sequence conversion modes***

Revisions Affected B

Description When the ADC is configured in repeat single, sequence, or repeat sequence conversion modes with trigger policy as trigger next in the MEMCTLx register, software attempting to stop the conversion sequence by clearing the ENC bit does not clear the BUSY bit in the STATUS register. In the case of sequence conversion mode with trigger next policy, the BUSY bit is cleared at the end of the conversion sequence.

Workaround To stop the conversions and to clear the BUSY bit in the above-mentioned ADC operating scenario, the following software sequence can be followed.

1. Write CTL0.ENC = 0
2. Change CTL1.TRIGSRC to SOFTWARE
3. Write CTL1.SC=1

BATMON_01 *Incorrect temperature measurement*

Revisions Affected B

Description BATMON can report incorrect temperatures when hysteresis is enabled. To prevent potential incorrect temperature reports, the user must always disable BATMON hysteresis.

Workaround Hysteresis is controlled by the PMUD.CLT[2] HYST_EN bit.

Hysteresis is enabled by default (reset value = 1) and, therefore, must actively be disabled during boot.

Hysteresis can be disabled by clearing the PMUD.CLT[2] HYST_EN bit using the following command:

```
HWREG( PMUD_BASE + PMUD_O_CTL ) = ( PMUD_CTL_CALC_EN |  
PMUD_CTL_MEAS_EN )
```

This workaround is incorporated into the SimpleLink™ Low Power F3 software development kit (SDK) version 9.11 and newer.

BATMON_02 *Spurious temperature update interrupts from BATMON in standby.*

Revisions Affected B**Description** BATMON can issue spurious temperature update interrupts when PMUD.EVENT.TEMP_UPDATE is used as a wake-up source from standby.**Workaround** Instead of using PMUD.EVENT.TEMP_UPDATE as the wake-up source, PMUD.EVENT.TEMP_OVER_UL (current temperature over a set upper limit) or PMUD.EVENT.TEMP_BELOW_LL (current temperature below a set lower limit) shall be considered.

When using PMUD.EVENT.TEMP_OVER_UL or PMUD.EVENT.TEMP_BELOW_LL as wake-up interrupts, these are the other settings that have to be enabled:

- Select GLDO as the source for VDDR regulation by setting PMCTL.VDDRCTL.SELECT to 0x0.

Note

This causes a slight increase in standby power consumption. Please check the 'Power Consumption – Power Modes' section of the data sheet for exact details.

- Set SYS0.TMUTE4.RECHCOMPREFLVL to 0x2
- Set SYS0.TMUTE5.GLDOISSET to 0x1E

This workaround would be incorporated into future releases of SimpleLink™ Low Power F3 software development kit (SDK).

SYS_204	<i>SysTimer may not always generate a compare event when previously programmed with a value.</i>
Revisions Affected	B
Description	SysTimer does not always generate a compare event during the initialization/sync up phase, when SysTimer has previously been programmed with a value.
Workaround	Wait to program SysTimer until SYSTIM.STATUS.SYNCUP is cleared. This workaround is incorporated into the SimpleLink™ Low Power F3 software development kit (SDK) version 9.11 and newer.

SYS_206 ***The RF phase jumps during HFXT amplitude compensation and HFXT amplitude control.***

Revisions Affected B**Description** The RF phase jumps during HFXT amplitude compensation and HFXT amplitude control. This issue only applies after the start-up of the device is complete, and then later programmatically adjusting the cap array values while using HFXT. If the cap array values are set during startup, this issue is not seen.**Workaround** The setting or modification of cap array steps should only be done during start-up and before any RF operations. Do not modify the cap array steps dynamically during run-time after that point. The Q1 and Q2 cap array steps can be modified in SysConfig.

SYS_207

Standby entry may not be gated if the FLTSETTLED bit is read too soon.

Revisions Affected B

Description

Standby entry may not be gated if attempted before the LFINC filter settles and is read too soon. This issue is not seen when using LFXT.

Workaround

To workaround this, when using LFOSC:

1. Clear both the interrupts.
2. Check for CKMD.RIS.HFXTGOOD.
3. Check for CKMD.RIS.LFTICK.
4. Check for FLTSETTLED.

Standby entry should be triggered only when the LFINC filter has settled, which can be confirmed by reading the memory masked register (MMR) CKMD.LFCLKSTAT.FLTSETTLED bit.

Alternatively, LFXT can be used, and this can be avoided. This workaround is incorporated into the SimpleLink™ Low Power F3 software development kit (SDK) version 9.11 and newer.

UDMA_01 ***μDMA write response to a peripheral's single request can be missed.***

Revisions Affected B**Details**

μDMA responds to single and burst requests from peripherals. In case the write access(es) from μDMA is(are) intercepted by the interconnect write buffers due to arbitration loss, the peripheral can raise a second spurious single or burst request. Since the μDMA responds to the second request after the peripheral's FIFO gets full with earlier write buffer contents, the second write(s) is(are) ignored by the peripheral and get(s) missed. This issue is seen only during data transfers via μDMA TX channels. This issue is not seen on the μDMA RX channels, since the read path through the interconnect does not include write buffers.

Workaround

μDMA SETBURST is configured to use BURST requests.

μDMA arbitration size is 2.

The TX FIFO level trigger is set to $\leq 1/4$ empty.

This workaround is incorporated into the SimpleLink™ Low Power F3 software development kit (SDK) version 9.11 and newer.

IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATASHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, regulatory or other requirements.

These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you fully indemnify TI and its representatives against any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to [TI's Terms of Sale](#), [TI's General Quality Guidelines](#), or other applicable terms available either on ti.com or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products. Unless TI explicitly designates a product as custom or customer-specified, TI products are standard, catalog, general purpose devices.

TI objects to and rejects any additional or different terms you may propose.

Copyright © 2026, Texas Instruments Incorporated

Last updated 10/2025