

TVP5145
Firmware v6.00
Errata

Contents

1	Introduction.....	3
2	Identifying the Device Revision and Firmware Version	3
3	Firmware Problems Resolved with Register Accesses	4
	3.1 Changing Input Type from Composite (CVBS) to S-Video	4
	3.1.1 Required Register Accesses	4
	3.2 Changing Input Type from YPbPr to S-Video	4
	3.2.1 Required Register Accesses	4
	3.3 Automatic Color Gain Control (ACGC) is Not Enabled by Default	4
	3.3.1 Required Register Accesses	4
	3.4 Fast Lock is Not Enabled by Default	4
	3.4.1 Required Register Accesses	4
4	Firmware Problems Resolved with PatchCode	5
5	Unresolved Firmware Problems	6
	5.1 Image Instability When Square Pixel Sampling PAL-M S-Video Input Signals	6
6	Technical Support	6

1 Introduction

The firmware, internal to the TVP5145, is responsible for the various algorithms, functions and controls of the device. This firmware is executed from the device's internal ROM. The device itself also has an additional 5K-bytes of RAM. This RAM is reserved to fix any ROM firmware problems not addressed with simple register accesses. The RAM is referred to as PatchRAM. The code executed from the PatchRAM is referred to as PatchCode.

This document describes the known problems in the firmware, version 6.00 of the TVP5145. The problems are resolvable with simple register accesses.

Use of the PatchRAM is *not* required for version 6.00 of the TVP5145. Please see below for details. To easier customer designs, Texas Instruments also developed an alternative PatchCode solution, version 6.02, which is available for download at:

<http://focus.ti.com/docs/prod/productfolder.jhtml?genericPartNumber=TVP5145>

under *Development Tools*.

Examples given in this document assume I2C communication.

2 Identifying the Device Revision and Firmware Version

Users need to check the device revision or firmware version before applying the solutions described in this document. Previous revisions of TVP5145 devices have different firmware versions which require different solutions to fix the problems. The firmware version 6.00 devices have a mark of "U1.3-B" on the device. The firmware version of the TVP5145 can be determined by reading I2C/PHI registers. Reading address 80h, the major version register, and 87h, the minor version register, should display firmware version 6.00, or values of 0x06 and 0x00 respectively.

3 Firmware Problems Resolved with Register Accesses

The following problems can be resolved by writing to various I2C/PHI registers. The register accesses required are described in detail below.

3.1 Changing Input Type from Composite (CVBS) to S-Video

When changing the input type from composite (CVBS) to S-video, there is a loss of color lock in the S-video.

3.1.1 Required Register Accesses

To resolve this, it is necessary to first program register address 20h and then register address 00h. This will prevent a loss of color lock when changing CVBS input to S-video input.

3.2 Changing Input Type from YPbPr to S-Video

When changing the input type from component to S-video, there is a loss of color lock in the S-video.

3.2.1 Required Register Accesses

To resolve this, it is necessary to first select a composite (CVBS) video input and then select S-video. This will correct the loss of color lock. The CVBS input does not have to have a signal present.

3.3 Automatic Color Gain Control (ACGC) is Not Enabled by Default

By default, the ACGC is not enabled.

3.3.1 Required Register Accesses

To resolve this, it is necessary to set register address 1Ah, bits 1 and 0, to 00.

3.4 Fast Lock is Not Enabled by Default

By default, the Fast Lock option is not enabled. This affects the switching time between inputs.

3.4.1 Required Register Accesses

To resolve this, it is necessary to set register address 25h, bit 0, to 1.

4 Firmware Problems Resolved with PatchCode

The problems described in the previous section are also fixed in the 6.02 version of the PatchCode. When using PatchCode solution, it is no need to apply the Register Accesses solutions described above.

The PatchCode is approximately 5kB in size. In order to use the PatchCode, your system must be able to store data of this size including any additional register settings.

The following is pseudo code that illustrates how the PatchRAM should be used. The PatchCode is loaded into the TVP5145 PatchRAM in much of the same way a typical I2C register write is performed.

```
// This is the PatchCode listed in data bytes
unsigned char T5145_PH[] =
{
0x0A,
0x00,
0x00,
.
.
.
0x0F,
0x54,
0xCF
};

// Start TVP5145 CPU
TVP5145_I2C_Write( 0x7F, 0x00 );

// Read ROM version registers
nMajorVersion = TVP5145_I2C_Read( 80h );
nMinorVersion = TVP5145_I2C_Read( 87h );

// ROM 1.3 = Firmware version 06.00

if( ( nMajorVersion == 0x06 ) && ( nMinorVersion == 0x00 ) )
{
    // Load TVP5145 patch code for ROM version 1.3
    // CPU goes into reset state when code download begins
    // 0x7E is the PatchRAM address byte
    TVP5145_I2C_Write( 0x7E, T5145_PH );

    // Restart CPU
    TVP5145_I2C_Write( 0x7F, 0x00 );
}

// Initialize registers as usual; these are examples only
TVP5145_I2C_Write( 0x00, 0x00 ); // Select VI1A composite video
TVP5145_I2C_Write( 0x20, 0x00 );

TVP5145_I2C_Write( 0x0D, 0x47 ); // Set to ITU-R BT.601 sampling rate,
// ITU-R BT.656 format
```

5 Unresolved Firmware Problems

The following problems are observed with the firmware 6.00 device. Currently these problems are unresolved.

5.1 Image Instability When Square Pixel Sampling PAL-M S-Video Input Signals

When the video signals are PAL-M system though S-video input, using square pixel sampling may cause the video image unstable for some video sources. This problem is not fixed in the above solutions. However, the problem is found to be limited only to this specific combination: PAL-M, S-video, and square pixel.

6 Technical Support

For technical support, please visit www.ti.com/sc/support.

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

Mailing Address:

Texas Instruments
Post Office Box 655303
Dallas, Texas 75265