

TMS320LC2406A, TMS320LC2404A, TMS320LC2402A

DSP Controllers

Silicon Errata

SPRZ185C
May 2001
Revised June 2004



Copyright © 2004, Texas Instruments Incorporated

Contents

1	Introduction	3
1.1	Quality and Reliability Conditions	3
	TMX Definition	3
	TMP Definition	3
	TMS Definition	3
1.2	Revision Identification	3
2	Known Design Marginality/Exceptions to Functional Specifications	5
2.1	Advisories for Revisions 1.0 and 2.0	5
	LPM1 Mode With an External Crystal/Resonator	5
	Internal Oscillator	5
	ADC — ADC Sequencer Operation	6
	CAN — CAN Bit Timing	6
	CAN — Method to Service Multiple Interrupts Through the Existing Two-Interrupt Structure	6
	EV-CAPn Input	7
	PDPINTx Pin Operation	7
	QEP Circuit	7
	SPISTE Timing Anomaly	8
2.2	Advisories for Revision 1.0	8
	CSM — Code Security Module	8
	Peripheral Clocks Not Turned Off in LPM1	9
	ADC — ADC Module Clock Not Turned Off	9
3	Documentation Support	10

1 Introduction

This document describes the silicon updates to the functional specifications for the TMS320LC2406A, TMS320LC2404A, and the TMS320LC2402A DSP Controllers, silicon revision 1.0 and 2.0. The updates are applicable to:

- TMS320LC2406A (100-pin LQFP, PZ suffix)
- TMS320LC2404A (100-pin LQFP, PZ suffix)
- TMS320LC2402A (64-pin QFP, PG suffix)

1.1 Quality and Reliability Conditions

TMX Definition

Texas Instruments (TI) does not warranty either (1) electrical performance to specification, or (2) product reliability for products classified as “TMX.” By definition, the product has not completed data sheet verification or reliability performance qualification according to TI Quality Systems Specifications.

The mere fact that a “TMX” device was tested over a particular temperature range and voltage range should not, in any way, be construed as a warranty of performance.

TMP Definition

TI does not warranty product reliability for products classified as “TMP.” By definition, the product has not completed reliability performance qualification according to TI Quality Systems Specifications; however, products are tested to a published electrical and mechanical specification.

TMS Definition

Fully-qualified production device.

1.2 Revision Identification for TMS320LC2404A/2406A

The device revision can be determined by the lot trace code marked on the top of the package. The location of the lot trace code is shown in Figure 1.




Figure 1. Example of Lot Trace Code for TMS320LC2404A/2406A

All trademarks are the property of their respective owners.

Second Letter in Prefix of Lot Trace Code	Silicon Revision	Comments
Blank (no first letter in prefix)	Indicates Revision 1.0	This silicon revision is available as TMS.
A (first letter in prefix is a "C" and the second is an "A")	Indicates Revision 2.0	This silicon revision is available as TMS.

1.3 Revision Identification for TMS320LC2402A




Figure 2. Example of Lot Trace Code for TMS320LC2404A/2402A

Second Letter in Prefix of Lot Trace Code	Silicon Revision	Comments
A (Second letter in prefix)	Indicates Revision 1.0	This silicon revision is available as TMS.
B (First letter in prefix is a "C" and the second is an "B")	Indicates Revision 2.0	This silicon revision is available as TMS.

2 Known Design Marginality/Exceptions to Functional Specifications

Table 1. Summary of Exceptions

Description	Revision(s) Affected	Page
LPM1 Mode With an External Crystal/Resonator	1.0, 2.0	5
Internal Oscillator	1.0, 2.0	5
ADC — ADC Sequencer Operation	1.0, 2.0	6
CAN — CAN Bit Timing	1.0, 2.0	6
CAN — Method to Service Multiple Interrupts Through the Existing Two-Interrupt Structure	1.0, 2.0	6
EV–CAPn Input	1.0, 2.0	7
PDPINTx Pin Operation	1.0, 2.0	7
QEP Circuit	1.0, 2.0	7
SPISTE Timing Anomaly	1.0, 2.0	8
CSM — Code Security Module	1.0	9
Peripheral Clocks Not Turned Off in LPM1	1.0	9
ADC — ADC Module Clock Not Turned Off	1.0	9

2.1 Advisories for Revisions 1.0 and 2.0

Advisory

LPM1 Mode With an External Crystal/Resonator

Revision(s) Affected: 1.0, 2.0

Details: The device does not come out of LPM1 mode when the internal oscillator (in conjunction with an external crystal/resonator) is used. This is not an issue if an external oscillator is used.

Workaround: Do not use LPM1 if using the internal oscillator.

Advisory

Internal Oscillator

Revision(s) Affected: 1.0, 2.0

Details: The internal oscillator of the 240xA device has a design marginality that may prevent the internal oscillator from starting upon power-up under certain conditions pertaining to board layout, ground bounce, and power-supply ramp rate. This is a concern only when the internal oscillator is used in conjunction with an external quartz crystal/ceramic resonator and not with an external oscillator.

Workaround: Use of a 1M-Ω resistor in parallel with the crystal across the XTAL1 and XTAL2 pins removes this condition.

Advisory*ADC — ADC Sequencer Operation*

Revision(s) Affected: 1.0, 2.0

Details: The ADC sequencer operation has an issue when $CPS = 1$ and $ACQ_Prescaler = 0$. When an ADC sequence is started, the sequence stops after performing the first conversion. For example, if there are five conversions programmed for a sequence, the sequencer may stop after performing the first conversion. When $CPS = 0$, all the conversions are performed. The issue surfaces only when $CPS = 1$ and $ACQ_Prescaler = 0$. CPS can be 1 for any other $ACQ_Prescaler$ value.

Workaround: $ACQ_Prescaler = 0$ should not be used in conjunction with $CPS = 1$.

Advisory*CAN — CAN Bit Timing*

Revision(s) Affected: 1.0, 2.0

Details: When the SBG bit (bit 10 of the BCR1 register) is set to 1, the “high” bit may be one TQ shorter/longer than it should be.

Workaround: Set $SBG = 0$.

Advisory*CAN — Method to Service Multiple Interrupts Through the Existing Two-Interrupt Structure*

Revision(s) Affected: 1.0, 2.0

Details: A CAN module interrupt will not assert a core-level interrupt if a CAN_IFR bit (set by any previous CAN interrupt) still remains set at the time of occurrence of the new interrupt. For example, when a new CAN interrupt is asserted before the processor has had a chance to clear the CAN_IFR bit that caused the interrupt to happen, the CAN module does not assert a core-level CPU interrupt ($INTn$) for the new interrupt and may “lose” interrupts. However, the occurrence of any interrupt-causing event will always set the appropriate flag bit in the CAN_IFR register.

Workaround: The CAN_IFR bit that causes an interrupt must be cleared as early as possible within the ISR. This can be done by copying the CAN_IFR register to a memory variable and then clearing the set bit. The memory variable can then be examined to determine which interrupt was asserted. If all CAN_IFR bits are cleared (i.e., zero) when a “new” interrupt is asserted, the “new” interrupt will be recognized and serviced by the core.

Advisory

EV-CAPn Input

Revision(s) Affected: 1.0, 2.0

Details: If a CAPn input is high while the capture units are being enabled, it triggers spurious captures. The CAPFIFO status bits would indicate that there are two words in the FIFO when, in reality, no capture was triggered. If the capture interrupt is enabled, it will trigger the capture interrupt as well.

Workaround: Initialize the CAPFIFO status bits (and enable the capture interrupt) after configuring the capture units.

Advisory

 $\overline{\text{PDPINTx}}$ Pin Operation

Revision(s) Affected: 1.0, 2.0

Details: If the $\overline{\text{PDPINTx}}$ pin is active during a device reset, it prevents the recognition of valid PDPINTx interrupts in the future.

Workaround: To overcome this problem, bit PIRQR0.0 (for $\overline{\text{PDPINTA}}$) and bit PIRQR2.0 (for $\overline{\text{PDPINTB}}$) need to be cleared to zero. This can be achieved by writing a zero to these bits or by writing a one to the corresponding PIAACKRn.0 bits. In addition to this, the EVAIFRA.0 bit (or EVBIFRA.0 bit) should be cleared as appropriate.

The PIRQRn and PIAACKRn registers are *not* intended to be used in user applications. The workaround mentioned herein is a special case during the initialization of the device. After initialization, these registers should not be used by the user code.

Advisory

QEP Circuit

Revision(s) Affected: 1.0, 2.0

Details: After a DSP reset, the QEP module fails to detect the first transition that occurs on QEP input pins. Therefore, if the first transition occurs after a GP Timer has been initialized and enabled as the QEP counter (i.e., to use QEP as source of clock), the first transition will not be counted by the GP Timer. The result is an error of one count in the GP Timer out of a total of 1024 counts for a 256-line encoder, or 4096 counts for a 1024-line encoder. However, the issue is not a concern under any of the following conditions:

1. *The first transition happens **before** the GP Timer is initialized and enabled as QEP counter.* This ensures that all transitions are counted after initialization.
2. *After the first index pulse is received and if the index pulse is used to recalibrate the GP Timer (through capture interrupt).* The recalibration corrects the error in the GP Timer; therefore, from the time the first index pulse is received, the QEP counter becomes accurate.

QEP Circuit (Continued)

- Workaround(s):**
1. Make the first transition happen before the GP timer is initialized and enabled as QEP counter. This is usually the case because typically the rotor shaft is locked to a known position before the GP Timer is initialized. Locking the rotor shaft will generate transitions on QEP input pins, unless the rotor shaft is exactly aligned to the known position (which is a rare case). Disturbing the rotor shaft on purpose takes care of the rare case.
 2. Use the index pulse of the encoder to recalibrate the GP Timer used as QEP counter.

AdvisorySPISTE Timing Anomaly

Revision(s) Affected: 1.0, 2.0

Details: The SPISTE signal has a timing anomaly because of which it goes high sooner than it should (i.e., before the last bit has ended). This results in unreliable read of the last bit of the word by both the master and the slave. Following is a summary of the bug description depending on which SPI clocking scheme is used:

- **CLOCK POLARITY = 0, PHASE = 0**
The SPISTE signal goes high 3 CPU clock cycles after the falling edge of the SPICLK for the last bit of transmission.
- **CLOCK POLARITY = 0, PHASE = 1**
The SPISTE signal goes high 3 CPU clock cycles after the rising edge of the SPICLK for the last bit of transmission.
- **CLOCK POLARITY = 1, PHASE = 0**
The SPISTE signal goes high 3 CPU clock cycles after the rising edge of the SPICLK for the last bit of transmission.
- **CLOCK POLARITY = 1, PHASE = 1**
The SPISTE signal goes high 3 CPU clock cycles after the falling edge of the SPICLK for the last bit of transmission.

Note that the timing issue is aggravated when PHASE = 1, since the time window for which the SPISTE signal is valid for the last bit gets reduced further.

Workaround: The SPISTE pin should be used in its GPIO configuration. This pin can then be manipulated manually in software. Note that this workaround does not require any hardware change.

2.2 Advisories for Revision 1.0

Advisory*CSM — Code Security Module***Revision(s) Affected:** 1.0**Details:** Unsecuring a secured part does not work as documented.**Workaround:** This has been fixed in the next revision of the silicon.**Advisory***Peripheral Clocks Not Turned Off in LPM1***Revision(s) Affected:** 1.0**Details:** Clocks to peripheral modules are not automatically turned off in LPM1.**Workaround:** Clocks must be turned off by the code prior to entering LPM1. This has been fixed in the next revision of the silicon.**Advisory***ADC — ADC Module Clock Not Turned Off***Revision(s) Affected:** 1.0**Details:** Clock to the ADC module is not turned off even when bit 7 of the SCSR1 register is cleared.**Workaround:** This has been fixed in the next revision of the silicon.

3 Documentation Support

For device-specific data sheets and related documentation, visit the TI web site at: <http://www.ti.com>

To access documentation on the web site:

1. Go to <http://www.ti.com>
2. Click on **DSP Product Tree**
3. Click on the **C2000** tab
4. Click on **TMS320C24x DSP Generation**
5. Click on a device name and then click on the documentation type you prefer.

For further information regarding the TMS320LC2406A, TMS320LC2404A, and TMS320LC2402A devices, please refer to the following publications:

- *TMS320LF/LC240xA DSP Controllers Reference Guide: System and Peripherals* (literature number SPRU357)
- Manual Update Sheet for *TMS320LF/LC240xA DSP Controllers Reference Guide: System and Peripherals* (SPRU357B) [literature number SPRZ015]
- *TMS320F/C24x DSP Controllers Reference Guide: CPU and Instruction Set* (literature number SPRU160)
- *3.3V DSP for Digital Motor Control* application report (literature number SPRA550)
- *TMS320LF2407A, TMS320LF2406A, TMS320LF2403A, TMS320LF2402A, TMS320LC2406A, TMS320LC2404A, TMS320LC2402A DSP Controllers* data sheet (literature number SPRS145)

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

Products		Applications	
Amplifiers	amplifier.ti.com	Audio	www.ti.com/audio
Data Converters	dataconverter.ti.com	Automotive	www.ti.com/automotive
DSP	dsp.ti.com	Broadband	www.ti.com/broadband
Interface	interface.ti.com	Digital Control	www.ti.com/digitalcontrol
Logic	logic.ti.com	Military	www.ti.com/military
Power Mgmt	power.ti.com	Optical Networking	www.ti.com/opticalnetwork
Microcontrollers	microcontroller.ti.com	Security	www.ti.com/security
		Telephony	www.ti.com/telephony
		Video & Imaging	www.ti.com/video
		Wireless	www.ti.com/wireless

Mailing Address: Texas Instruments
Post Office Box 655303 Dallas, Texas 75265