

TAS5508A Errata

1 Bass/Treble Filter Set

1.1 Problem Description

The TAS5508A has an intermittent problem when writing to the treble and bass filter-set registers or when a sample-rate change occurs which causes the bank switching in the TAS5508A to write these registers.

1.2 System Impact

Audio might be corrupted in a few channels.

1.3 Workaround

The filter-set registers should be written twice with at least 1.375 ms (66 LRCLKs @ 48 kHz) between writes. The high-pass filter should be enabled to prevent dc output. Do not use bass/treble filter-set update as a part of bank switching.

1.4 Comments

This issue will be corrected in all future releases of this device.

2 PWM Channels Shut Down

2.1 Problem Description

A PWM channel could lose output if, following a sample-rate-change event, another sample-rate-change event occurs while the volume unmute transition is in progress (volume is muted and then unmuted for a sample-rate change).

2.2 System Impact

One PWM channel could lose its audio output.

2.3 Workaround

Enable the hard unmute bit to minimize the chance of occurrence during a sample-rate change.

2.4 Comments

This issue will be corrected in all future releases of this device.

3 Soft Mute

3.1 Problem Description

If the output mixer has a nondefault configuration, then an incorrect PWM channel stops as a response to channel mute.

3.2 System Impact

Wrong channels mutes when MUTE command is issued. So, channel soft mute should not be used with output mixing.

3.3 Workaround

Use a low channel volume (Master + Ch > -109 dB; 0x1FC) and enable automute, or do not use output mixing.

3.4 Comments

This issue will be corrected in all future releases of this device.

4 Channel-4 Audio Corruption

4.1 Problem Description

Occasionally, the channel-4 biquad becomes corrupted when a DAP coefficient update occurs during a volume ramp.

4.2 System Impact

When this problem occurs, channel-4 audio is corrupted.

4.3 Workaround

Wait until volume ramp is complete to write any DAP coefficient. Time is slew-rate dependent, as set in register 0xD0.

4.4 Comments

This issue will be corrected in all future releases of this device.

5 AM-Mode Disable

5.1 Problem Description

The TAS5508A continues to use the AM-mode switching frequency even after the AM-mode disable bit has been set.

5.2 System Impact

The TAS5508A remains at the AM-mode switching frequency, which could result in decreased dynamic range.

5.3 Workaround

1. Put the TAS5508A in mute. Write to register 0xD9 (data = 0x0000 0245).
2. Write to register 0x2F (data = 0x81).
3. Write to register 0x00 (data = 0x6D).
4. Write to register 0xDE (data = 0x0010 0520).
5. Write to AM interference avoidance register to disable AM interference. Write to register 0xDE (data = 0x0000 0000).
6. Write to register 0x2F (data = 0x80).
7. Write to register 0x2F (data = 0x00).
8. Unmute the TAS5508A. Write original volume value to register 0xD9.

5.4 Comments

This issue will be corrected in all future releases of this device.

6 PSVC Control when Using Subwoofer as Lineout

6.1 Problem Description

Volume corruption can occur when the subwoofer is configured as lineout while PSVC is enabled.

One of the PSVC modes is called *subwoofer not part of PSVC calculation*. Normally, this mode is used when the subwoofer is configured as lineout. However, an audible problem occurs during volume changes. In this case, the subwoofer is always used for PSVC calculation even though it is configured not to do so (e.g., as lineout). So, during the volume ramp, the transient values are not correct, thereby creating audible artifacts.

6.2 System Impact

When the subwoofer is configured as lineout with PSVC enabled, audible artifacts can occur during volume changes.

6.3 Workaround

None. The subwoofer cannot be used as lineout if PSVC is enabled.

7 Use of 5-V CMOS I²C Drivers

7.1 Problem Description

In systems using 5-V CMOS buffers for the I²C interface, special pullup resistors are required.

The I²C specification requires that V_{IH} is $0.7 \times V_{DD} = 3.5$ V when V_{DD} is 5 V. In some 5-V CMOS systems, the normal value for the I²C pullup resistor is 4.7 k Ω . This could cause the voltage not to rise above 3.47 V, which violates the specification. The root cause has been identified as a TAS5508B 5-V-tolerant buffer issue.

7.2 System Impact

1. No impact for 3.3-V operation.
2. No impact for TTL operation.
3. Impact only for 5-V CMOS operation where V_{IH} could be lower than the specification of 3.5 V.

7.3 Workaround

It is recommended that the I²C pullup resistors R_P be 3.3 k Ω (see Figure 1). If there is a series resistor in the circuit (see Figure 2), then the series resistor R_S should be less than or equal to 300 Ω .





Figure 1. I²C Pullup Circuit (With No Series Resistor)



(1) $V_S = 5 \times R_S / (R_S + R_P)$. When driven low, $V_S \ll V_{IL}$ requirements.

(2) $R_S \leq 300 \Omega$

Figure 2. I²C Pullup Circuit (With Series Resistor)

8 One-Sample Delay in Channels 3, 4, 7, and 8

8.1 Problem Description

The TAS5508A exhibits a one-sample delay on channels 3, 4, 7, and 8 for sample rates of 32, 44.1, and 48 kHz. The delay occurs in the PWM section.

8.2 System Impact

This time misalignment can impact applications where the TAS5508A is used to provide crossover filtering and bi-amplification, as in powered loudspeakers. The problem that occurs in these cases is that a one-sample time delay between either the high-pass or low-pass path causes an error in the overall crossover frequency response.

The one-sample delay is not anticipated to cause any impact in other applications, because this corresponds to relatively small position change, 7,19 mm or 0.28 in. for a 48-kHz sample rate.

8.3 Workaround


The time misalignment can be corrected by using a biquad to provide a one-sample delay for each of the nondelayed PWM channels for the 48-, 44.1-, and 32-kHz sample rates.

An example of this solution is the following:

When the 8×2 crossbar mixer provides a 1:1 input-to-output connection, an eight-channel loudspeaker configuration uses one of the seven biquads in channels 1, 2, 5, and 6 to provide a one-sample delay.

To produce a one-sample delay with one of the TAS5508A biquads:

1. Set the b_1 biquad coefficients to a gain of 1.
2. Set all of the other biquad coefficients (b_0 , b_2 , a_1 , and a_2) to a gain of 0, as shown in the following diagram and table.



M0012-01

The one-sample delay setting is programmed using the following I²C register settings.

I ² C SUBADDRESS	COEFFICIENT	HEX VALUE
Biquad I ² C register Subaddress N	b_0 — $u(31:28)$, $b_0(27:24)$, $b_0(23:16)$, $b_0(15:8)$, $b_0(7:0)$	0x00, 0x00, 0x00, 0x00
	b_1 — $u(31:28)$, $b_1(27:24)$, $b_1(23:16)$, $b_1(15:8)$, $b_1(7:0)$	0x00, 0x80, 0x00, 0x00
	b_2 — $u(31:28)$, $b_2(27:24)$, $b_2(23:16)$, $b_2(15:8)$, $b_2(7:0)$	0x00, 0x00, 0x00, 0x00
	a_1 — $u(31:28)$, $a_1(27:24)$, $a_1(23:16)$, $a_1(15:8)$, $a_1(7:0)$	0x00, 0x00, 0x00, 0x00
	a_2 — $u(31:28)$, $a_2(27:24)$, $a_2(23:16)$, $a_2(15:8)$, $a_2(7:0)$	0x00, 0x00, 0x00, 0x00

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

Products		Applications	
Amplifiers	amplifier.ti.com	Audio	www.ti.com/audio
Data Converters	dataconverter.ti.com	Automotive	www.ti.com/automotive
DSP	dsp.ti.com	Broadband	www.ti.com/broadband
Interface	interface.ti.com	Digital Control	www.ti.com/digitalcontrol
Logic	logic.ti.com	Military	www.ti.com/military
Power Mgmt	power.ti.com	Optical Networking	www.ti.com/opticalnetwork
Microcontrollers	microcontroller.ti.com	Security	www.ti.com/security
		Telephony	www.ti.com/telephony
		Video & Imaging	www.ti.com/video
		Wireless	www.ti.com/wireless

Mailing Address: Texas Instruments
Post Office Box 655303 Dallas, Texas 75265

Copyright © 2006, Texas Instruments Incorporated