

TMS320LF2402
DSP Controller
Silicon Errata

SPRZ157K
February 2000
Revised July 2003



Copyright © 2003, Texas Instruments Incorporated

Contents

1	Introduction	3
1.1	Quality and Reliability Conditions	3
	TMX Definition	3
	TMP Definition	3
	TMS Definition	3
1.2	Revision Identification	4
2	Known Design Marginality/Exceptions to Functional Specifications	5
	Internal Oscillator	5
	ADC – Calibration	6
	ADC – Self-Test	6
	ADC – Start of Conversion	6
	EV – CAPn Input	7
	EV – PDPINTx Pin Operation	7
	EV – QEP Circuit	8
	Phantom Interrupts While Using the Real-Time Monitor	8
	SCI – SCI TX_EMPTY	9
	SCSR1 – OSC FAIL FLAG and OSC FAIL RESET Bits	9
	SCSR1 – ILLADR Bit	9
	SPI – SPISTE Timing Anomaly	10
	WDCR – WDFLAG Bit (in WDCR Register)	10
	Flash Specification for Write/Erase Cycles	11
	Additional Wait-State During Flash Memory Access	11
	Test Conditions	11
	TMS320LF2402 Pin Changes	11
	CLKOUT	12
	Emulation and Debugger	12
	Watchdog Disable (WDDIS) Bit	13
3	Documentation Support	14
1	Introduction	3

1 Introduction

This document describes the silicon updates to the functional specifications for the TMS320LF2402 DSP Controller, silicon revisions 1.0 ,1.1, 1.2, 1.3, 1.4, and 1.6. The updates are applicable to:

- TMS320LF2402 (64-pin PQFP, PG suffix)

1.1 Quality and Reliability Conditions

TMX Definition

Texas Instruments (TI) does not warranty either (1) electrical performance to specification, or (2) product reliability for products classified as “TMX.” By definition, the product has not completed data sheet verification or reliability performance qualification according to TI Quality Systems Specifications.

The mere fact that a “TMX” device was tested over a particular temperature range and voltage range should not, in any way, be construed as a warranty of performance.

TMP Definition

TI does not warranty product reliability for products classified as “TMP.” By definition, the product has not completed reliability performance qualification according to TI Quality Systems Specifications; however, products are tested to a published electrical and mechanical specification.

TMS Definition

Fully-qualified production device.

1.2 Revision Identification

The device revision can be determined by the lot trace code marked on the top of the package. The location of the lot trace code for the PG package is shown in Figure 1.




Figure 1. Example, Lot Trace Code for TMX320LF2402 (PG)

Second Letter in Prefix of Lot Trace Code	Silicon Revision	Comments
Blank (no second letter in prefix)	Indicates Revision 1.0	This silicon revision is available as TMX only.
A (second letter in prefix is an "A")	Indicates Revision 1.1	This silicon revision is available as TMX only.
B (second letter in prefix is a "B")	Indicates Revision 1.2	This silicon revision is available as TMX only.
C (second letter in prefix is a "C")	Indicates Revision 1.3	This silicon revision is available as TMS.
D (second letter in prefix is a "D")	Indicates Revision 1.4	This silicon revision is available as TMS.
F (second letter in prefix is a "F")	Indicates Revision 1.6	This silicon revision is available as TMS.

NOTE: There is no Revision 1.5 silicon.

2 Known Design Marginality/Exceptions to Functional Specifications

Table 1. Summary of Exceptions

Description	Revision(s) Affected	Page
Internal Oscillator	1.0, 1.1, 1.2, 1.3, 1.4, and 1.6	5
ADC – Calibration	1.0, 1.1, 1.2, 1.3, 1.4, and 1.6	6
ADC – Self-Test	1.0, 1.1, 1.2, 1.3, 1.4, and 1.6	6
ADC – Start of Conversion	1.0, 1.1, 1.2, 1.3, 1.4, and 1.6	6
EV – CAPn Input	1.0, 1.1, 1.2, 1.3, 1.4, and 1.6	7
EV – PDPINTx Pin Operation	1.0, 1.1, 1.2, 1.3, 1.4, and 1.6	7
EV – QEP Circuit	1.0, 1.1, 1.2, 1.3, 1.4, and 1.6	8
Phantom Interrupts While Using the Real-Time Monitor	1.0, 1.1, 1.2, 1.3, 1.4, and 1.6	8
SCI – SCI TX_EMPTY	1.0, 1.1, 1.2, 1.3, 1.4, and 1.6	9
SCSR1 – OSC FAIL FLAG and OSC FAIL RESET Bits	1.0, 1.1, 1.2, 1.3, 1.4, and 1.6	9
SCSR1 – ILLADR Bit	1.0, 1.1, 1.2, 1.3, 1.4, and 1.6	9
SPI – SPISTE Timing Anomaly	1.0, 1.1, 1.2, 1.3, 1.4, and 1.6	10
WDCR – WDFLAG Bit (in WDCR Register)	1.0, 1.1, 1.2, 1.3, 1.4, and 1.6	10
Flash Specification for Write/Erase Cycles	1.3	11
Additional Wait-State During Flash Memory Access	1.0, 1.1, and 1.2	11
Test Conditions	1.0, 1.1, and 1.2	11
TMS320LF2402 Pin Changes	1.0, 1.1, and 1.2	11
CLKOUT	1.0	12
Emulation and Debugger	1.0	12
Watchdog Disable (WDDIS) Bit	1.0	13

Advisory

Internal Oscillator

Revision(s) Affected: 1.0, 1.1, 1.2, 1.3, 1.4, and 1.6

Details: The internal oscillator of the 2402 device has a design marginality that may prevent the internal oscillator from starting upon power-up under certain conditions pertaining to board layout, ground bounce, and power-supply ramp rate. This is a concern only when the internal oscillator is used in conjunction with an external quartz crystal/ceramic resonator and not with an external oscillator.

Workaround: Use of a 1M-Ω resistor in parallel with the crystal across the XTAL1 and XTAL2 pins removes this condition.

Advisory

ADC – Calibration

Revision(s) Affected: 1.0, 1.1, 1.2, 1.3, 1.4, and 1.6

Details: The automatic calibration feature of the 240x ADC module exhibits occasional inconsistencies and hence should be avoided. The calibration feature can still be used with the restriction that the three internal reference points (V_{REFLO} , V_{REFHI} , and midpoint) should not be used. Therefore, bits 3, 2, and 1 of the ADCTRL1 register should be treated as reserved and must always be written with zeroes. The functionality of bit 14 of the ADCTRL2 register is now restricted to RST_SEQ1 (i.e., to reset sequencer 1).

Workaround: The calibration feature should only be used in a “manual” configuration. The user should connect the signal of interest (whose value is known), for which the offset needs to be determined. Once the offset is determined, it can be written into the CALIBRATION register. All subsequent conversion results will be adjusted by the offset as before. There is no need to be in the calibration mode to be able to write to the CALIBRATION register.

Advisory

ADC – Self-Test

Revision(s) Affected: 1.0, 1.1, 1.2, 1.3, 1.4, and 1.6

Details: The **self-test mode** of the ADC yields inconsistent results.

Workaround: The self-test mode should not be used. Bit 0 of ADCTRL1 should be treated as reserved and must always be written with zero.

Advisory

ADC – Start of Conversion

Revision(s) Affected: 1.0, 1.1, 1.2, 1.3, 1.4, and 1.6

Details: The **start of conversion** is unreliable when the Conversion Clock Prescale (CPS) bit in the ADCTRL1 register is 1, **and** when the acquisition prescaler is 0 (both conditions met). When CPS = 0, the ADC operation is not affected.

This bug only affects the ADC operation when the CPS bit is set ($ADCCLK = CLKOUT \div 2$). The bug causes the START signal, which is going to the analog portion of the A/D, to start a half-cycle of ADCCLK early and end a full cycle early. Thus, the acquisition window (which is the START signal plus one ADCCLK cycle) is a half-cycle shorter than it should be.

For the ACQ_PS3 to ACQ_PS0 bits (where ACQ_PSn = 1 through 15), this only affects the conversion time and source impedance. However, when ACQ_PSn = 0, a half-cycle shorter START bit causes the START signal to be active for only a half-cycle ... not long enough to ensure that a conversion will occur.

Workaround: ACQ_PS = 0 should **not** be used in conjunction with CPS = 1. This will be fixed in the 240xA silicon.

Advisory*EV – CAPn Input*

Revision(s) Affected: 1.0, 1.1, 1.2, 1.3, 1.4, and 1.6

Details: If a CAPn input is high while the capture units are being enabled, it triggers spurious captures. The CAPFIFO status bits would indicate that there are two words in the FIFO, when in reality, no capture was triggered. If the capture interrupt is enabled, it will trigger the capture interrupt as well.

Workaround: Initialize the CAPFIFO status bits (and enable the capture interrupt) after configuring the capture units.

Advisory*EV – $\overline{PDPINTx}$ Pin Operation*

Revision(s) Affected: 1.0, 1.1, 1.2, 1.3, 1.4, and 1.6

Details: If the $\overline{PDPINTx}$ pin is active during a device reset, it prevents the recognition of valid PDPINTx interrupts in the future.

Workaround: To overcome this problem, bit PIRQR0.0 (for $\overline{PDPINTA}$) and bit PIRQR2.0 (for $\overline{PDPINTB}$) need to be cleared to zero. This can be achieved by writing a zero to these bits or by writing a one to the corresponding PIACKRn.0 bits. In addition to this, the EVAIFRA.0 bit (or EVBIFRA.0 bit) should be cleared as appropriate.

The PIRQRn and PIACKRn registers are **not** intended to be used in user applications. The workaround mentioned herein is a special case during the initialization of the device. After initialization, these registers should not be used by the user code.

Advisory

EV – QEP Circuit

Revision(s) Affected: 1.0, 1.1, 1.2, 1.3, 1.4, and 1.6

Details: After a DSP reset, the QEP module fails to detect the first transition that occurs on QEP input pins. Therefore, if the first transition occurs after a GP Timer has been initialized and enabled as the QEP counter (i.e., to use QEP as source of clock), the first transition will not be counted by the GP Timer. The result is an error of one count in the GP Timer out of a total of 1024 counts for a 256-line encoder, or 4096 counts for a 1024-line encoder. However, the issue is not a concern under any of the following conditions:

1. *The first transition happens **before** the GP Timer is initialized and enabled as QEP counter.* This ensures that all transitions are counted after initialization.
2. *After the first index pulse is received and if the index pulse is used to recalibrate the GP Timer (through capture interrupt).* The recalibration corrects the error in the GP Timer; therefore, from the time the first index pulse is received, the QEP counter becomes accurate.

- Workaround(s):**
1. Make the first transition happen before the GP timer is initialized and enabled as QEP counter. This is usually the case because typically the rotor shaft is locked to a known position before the GP Timer is initialized. Locking the rotor shaft will generate transitions on QEP input pins, unless the rotor shaft is exactly aligned to the known position (which is a rare case). Disturbing the rotor shaft on purpose takes care of the rare case.
 2. Use the index pulse of the encoder to recalibrate the GP Timer used as QEP counter.

Advisory

Phantom Interrupts While Using the Real-Time Monitor

Revision(s) Affected: 1.0, 1.1, 1.2, 1.3, 1.4, and 1.6

Details: When the real-time monitor (RTM) is used, phantom interrupts may be occasionally seen—i.e., the PIVR register is loaded with 0000h when an interrupt is asserted. This problem is seen **only while debugging with the RTM** and is not applicable in actual applications.

Workaround: Check the PIVR value in the ISR. If a phantom interrupt is detected, return to the main code.

Advisory

SCI – SCI TX_EMPTY

Revision(s) Affected: 1.0, 1.1, 1.2, 1.3, 1.4, and 1.6**Details:** The TX_EMPTY bit (bit 6 in the SCICTL2 register) is supposed to get set when the transmit buffer and the shift register are **both** empty. However, this bit may occasionally be read as being set even when there is data in the transmit buffer.

Assuming two characters are being written back-to-back to the SCI, the TX_EMPTY bit is expected to go high after the second character is shifted out of the SCITXD pin. Occasionally, the TX_EMPTY bit goes high right after the first character is shifted out (i.e., when the second character is still in the transmit buffer). If the TX_EMPTY bit is polled to check the end-of-transmission of all characters, it may provide incorrect information about the status of the transmission.

Workaround: Follow these steps:

1. Read the TX_EMPTY bit.
2. If set, execute 2 NOPs and proceed to Step 3. Else, repeat Step 1.
3. Read the TX_EMPTY bit again.
4. If the bit is still set, then there are no more characters to be transmitted. If the bit is not set, it indicates transmission is not complete. Proceed to Step 1.

This will be fixed in the 240xA silicon.

Advisory

SCSR1 – OSC FAIL FLAG and OSC FAIL RESET Bits

Revision(s) Affected: 1.0, 1.1, 1.2, 1.3, 1.4, and 1.6**Details:** These bits do not work as intended. They will be marked as “reserved” in all future documentation.**Workaround:** None**Advisory**

SCSR1 – ILLADR Bit

Revision(s) Affected: 1.0, 1.1, 1.2, 1.3, 1.4, and 1.6**Details:** The ILLADR bit in the SCSR1 register may be set even though no illegal address access took place.

Workaround: This is a problem with the debugger-hardware interaction. This bit may be set on an emulation suspend such as a breakpoint or while single stepping. However, this bit works correctly in run time (i.e., this bit works correctly when the program is free-run without the JTAG connector being connected). This can be easily verified by writing a test code (running out of Flash) that copies the status of this bit to the XF bit and then monitoring the status of the XF pin using an oscilloscope.

Advisory*SPI – $\overline{\text{SPISTE}}$ Timing Anomaly*

Revision(s) Affected: 1.0, 1.1, 1.2, 1.3, 1.4, and 1.6

Details: The $\overline{\text{SPISTE}}$ signal has a timing anomaly due to which, it goes high sooner than it should (i.e., before the last bit has ended). This results in unreliable read of the last bit of the word by both the master and the slave. Following is a summary of the bug description depending on which SPI clocking scheme is used:

- **CLOCK POLARITY = 0, PHASE = 0**
The $\overline{\text{SPISTE}}$ signal goes high 3 CPU clock cycles after the falling edge of the SPICLK for the last bit of transmission.
- **CLOCK POLARITY = 0, PHASE = 1**
The $\overline{\text{SPISTE}}$ signal goes high 3 CPU clock cycles after the rising edge of the SPICLK for the last bit of transmission.
- **CLOCK POLARITY = 1, PHASE = 0**
The $\overline{\text{SPISTE}}$ signal goes high 3 CPU clock cycles after the rising edge of the SPICLK for the last bit of transmission.
- **CLOCK POLARITY = 1, PHASE = 1**
The $\overline{\text{SPISTE}}$ signal goes high 3 CPU clock cycles after the falling edge of the SPICLK for the last bit of transmission.

Note that the timing issue is aggravated when PHASE = 1, since the time window for which the $\overline{\text{SPISTE}}$ signal is valid for the last bit gets reduced further.

Workaround: The $\overline{\text{SPISTE}}$ pin should be used in its GPIO configuration. This pin can then be manipulated manually in software. Note that this workaround does not require any hardware change.

Advisory*WDCR – WDFLAG Bit (in WDCR Register)*

Revision(s) Affected: 1.0, 1.1, 1.2, 1.3, 1.4, and 1.6

Details: The power-on reset (POR) state of the WDFLAG bit is undefined. This could cause confusion if the user code attempts to differentiate a watchdog-initiated reset from a power-on reset.

Workaround: If an application implements a mechanism to differentiate a POR from other types of reset, the WDFLAG bit must be cleared after a POR. Once this is done, the WDFLAG bit can be set only by a watchdog reset.

Advisory*Flash Specification for Write/Erase Cycles***Revision(s) Affected:** 1.3**Details:** The minimum specification for endurance for the flash array (N_f) is 50 Write/Erase cycles.**Workaround:** This will be fixed in revision 1.4 of the silicon.**Advisory***Additional Wait-State During Flash Memory Access***Revision(s) Affected:** 1.0, 1.1, and 1.2**Details:** The DSP adds one wait-state for every read access of the Flash (i.e., CPU accesses to Flash memory are always at one wait-state). As a result of this, a program executed off Flash may take twice as long compared to external RAM. This affects *only* the Flash memory access time and does not affect DARAM, SARAM, external memory interface or peripheral registers.**Workaround:** This will be fixed in revision 1.3 of the silicon.**Advisory***Test Conditions***Revision(s) Affected:** 1.0, 1.1, and 1.2**Table 2. Test Conditions**

		NOM	MAX	UNIT	
T _A	Operating free-air temperature (excluding flash programming)	DSP Core	25	85	°C
		System and Peripherals	25		
V _{DD} , V _{DDO}	Supply voltage (3.3 V ±10%)	3.3-V operation	3.3		V
f _{CLKOUT}	Device clock frequency		30		MHz

Advisory*TMS320LF2402 Pin Changes***Revision(s) Affected:** 1.0, 1.1, and 1.2**Details:** The TMS320LF2402 pinout has changed with respect to the *TMS320LF2407*, *TMS320LF2406*, *TMS320LF2402 DSP Controllers* data sheet, literature number *SPRS094B* (September 1999). Pins 51 through 64 differ.**Workaround:** Refer to the new pinout in the current revision of the data sheet.

Advisory

CLKOUT

Revision(s) Affected: 1.0

Details: The 2402 CLKOUT rates differ from the data sheet specifications. The CLKOUT output has an additional $\div 2$ after the PLL module. CLKOUT is the same as the CPU clock.

Workaround: For *Silicon Revision 1.0*, use the crystal/resonator/oscillator with twice the specified frequency. For example, if 30-MHz CLKOUT is desired, use 15-MHz input clock instead of 7.5 MHz. Note that the PLL multiplication factor should be $\times 4$ to derive a 30-MHz CLKOUT from a 15-MHz input clock due to this bug. This will be fixed in the next revision of the silicon.

Table 3 shows the 3-bit ratio selection for various PLL output clock frequencies in *Silicon Revision 1.0*. These register bits are located in the SCSR1 register.

Table 3. Ratio Selection for Various PLL Output Clock Frequencies

CLK PS2	CLK PS1	CLK PS0	CPU Clock Frequency (CLKOUT) (F_{in} is input clock frequency)
0	0	0	$2 * F_{in}$
0	0	1	F_{in}
0	1	0	$0.67 * F_{in}$
0	1	1	$0.5 * F_{in}$
1	0	0	$0.4 * F_{in}$
1	0	1	$0.33 * F_{in}$
1	1	0	$0.29 * F_{in}$
1	1	1	$0.25 * F_{in}$

Advisory

Emulation and Debugger

Revision(s) Affected: 1.0

Details: In reference to the CLKOUT problem mentioned in the *CLKOUT* advisory, prototype boards or EVMs built for *Silicon Revision 1.0* may have debugger start-up problems.

Workaround: To avoid this problem, it is suggested that the device always be powered up in the *boot enable* mode (BOOT_EN pin low at reset). The boot code resets the watchdog and helps the debugger come up reliably. Once the debugger is up, the boot ROM can be disabled by writing a 0 to bit 3, the BOOT_EN bit, in the SCSR2 register. Debugging then works as normal.

This will be fixed in the next revision of the silicon.

Advisory*Watchdog Disable (WDDIS) Bit*

Revision(s) Affected: 1.0

Details: At reset, the watchdog override bit (WD OVERRIDE, bit 5 in the SCSR2 register) is set to 1. This allows the user to disable the watchdog by writing a 1 to the WDDIS bit (WDDIS, bit 6 in the WDCR register). Ideally, if the WD OVERRIDE bit is cleared by writing a 1, the user will not be able to disable the watchdog, even after writing a 1 to the WDDIS bit. In *Silicon Revision 1.0*, this feature does not work, i.e., the watchdog can be disabled by writing to the WDDIS bit, even if the WD OVERRIDE bit has been cleared.

Workaround: None. This will be fixed in the next revision of the silicon.

3 Documentation Support

For device-specific data sheets and related documentation, visit the TI web site at: <http://www.ti.com>

To access documentation on the web site:

1. Go to <http://www.ti.com>
2. Click on **DSP Product Tree**
3. Click on the **C2000** tab
4. Click on **TMS320C24x DSP Generation**
5. Click on a device name and then click on the documentation type you prefer.

For further information regarding the TMS320LF2402, please refer to the following publications:

- *TMS320LF/LC240xA DSP Controllers Reference Guide: System and Peripherals* (literature number SPRU357)
- Manual Update Sheet for *TMS320LF/LC240xA DSP Controllers Reference Guide: System and Peripherals* (SPRU357B) [literature number SPRZ015]
- *TMS320F/C24x DSP Controllers Reference Guide: CPU and Instruction Set* (literature number SPRU160)
- *3.3V DSP for Digital Motor Control* application report (literature number SPRA550)
- *TMS320LF2407, TMS320LF2406, TMS320LF2402 DSP Controllers* data sheet (literature number SPRS094)

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

Products		Applications	
Amplifiers	amplifier.ti.com	Audio	www.ti.com/audio
Data Converters	dataconverter.ti.com	Automotive	www.ti.com/automotive
DSP	dsp.ti.com	Broadband	www.ti.com/broadband
Interface	interface.ti.com	Digital Control	www.ti.com/digitalcontrol
Logic	logic.ti.com	Military	www.ti.com/military
Power Mgmt	power.ti.com	Optical Networking	www.ti.com/opticalnetwork
Microcontrollers	microcontroller.ti.com	Security	www.ti.com/security
		Telephony	www.ti.com/telephony
		Video & Imaging	www.ti.com/video
		Wireless	www.ti.com/wireless

Mailing Address: Texas Instruments
Post Office Box 655303 Dallas, Texas 75265

Copyright © 2003, Texas Instruments Incorporated