

**ABSTRACT**

This document describes the known exceptions to the functional specifications (advisories).

Table of Contents

1 Functional Advisories	1
2 Preprogrammed Software Advisories	3
3 Debug Only Advisories	3
4 Fixed by Compiler Advisories	3
5 Device Nomenclature	3
5.1 Device Symbolization and Revision Identification.....	3
6 Advisory Descriptions	5
7 Trademarks	31
8 Revision History	32

1 Functional Advisories

Advisories that affect the device operation, function, or parametrics.

✓ The check mark indicates that the issue is present in the specified revision.

Errata Number	Rev B (Prototype X-Marked Products)	Rev C
AES_ERR_01	✓	✓
BSL_ERR_01	✓	✓
BSL_ERR_02	✓	
COMP_ERR_06	✓	✓
CPU_ERR_02	✓	✓
CPU_ERR_03	✓	✓
FCC_ERR_01	✓	✓
FLASH_ERR_03	✓	✓
FLASH_ERR_04	✓	✓
FLASH_ERR_05	✓	✓
FLASH_ERR_08	✓	✓
FLASH_ERR_09	✓	✓
GPIO_ERR_05	✓	✓
GPIO_ERR_06	✓	✓
I2S_ERR_01	✓	✓
KEYSTORE_ERR_01	✓	✓
PMCU_ERR_14	✓	✓
PMCU_ERR_16	✓	✓
RST_ERR_01	✓	✓
RST_ERR_02	✓	✓
SPI_ERR_10	✓	✓

Errata Number	Rev B (Prototype X-Marked Products)	Rev C
SYSCTL_ERR_01	✓	✓
SYSCTL_ERR_02	✓	✓
SYSCTL_ERR_03	✓	✓
SYSCTL_ERR_04	✓	✓
SYSCTL_ERR_05	✓	✓
SYSCTL_ERR_06	✓	✓
SYSCTL_ERR_11	✓	✓
SYSCTL_ERR_12	✓	✓
SYSOSC_ERR_01	✓	✓
SYSOSC_ERR_02	✓	✓
SYSOSC_ERR_04	✓	✓
SYSOSC_ERR_05	✓	✓
SYSPLL_ERR_01	✓	
TIMER_ERR_04	✓	✓
TIMER_ERR_06	✓	✓
TIMER_ERR_07	✓	✓
UNICOMMI2CC_ERR_01	✓	✓
UNICOMMI2CC_ERR_02	✓	✓
UNICOMMI2CC_ERR_03	✓	✓
UNICOMMI2CT_ERR_01	✓	✓
UNICOMMI2CT_ERR_02	✓	✓
UNICOMMI2CT_ERR_03	✓	✓
UNICOMMSPI_ERR_01	✓	✓
UNICOMMSPI_ERR_02	✓	✓
UNICOMMSPI_ERR_03	✓	✓
UNICOMMSPI_ERR_04	✓	✓
UNICOMMUART_ERR_01	✓	✓
UNICOMMUART_ERR_02	✓	✓
UNICOMMUART_ERR_03	✓	✓
UNICOMMUART_ERR_04	✓	✓
UNICOMMUART_ERR_05	✓	✓
UNICOMMUART_ERR_06	✓	✓
UNICOMMUART_ERR_07	✓	✓
UNICOMMUART_ERR_08	✓	✓
UNICOMMUART_ERR_09	✓	✓
UNICOMMUART_ERR_10	✓	✓
UNICOMMUART_ERR_11	✓	✓
UNICOMMUART_ERR_12	✓	✓
UNICOMMUART_ERR_13	✓	✓
UNICOMMUART_ERR_14	✓	✓
UNICOMMUART_ERR_15	✓	✓
USB_ERR_01	✓	✓
USB_ERR_02	✓	✓
USB_ERR_03	✓	
USB_ERR_04	✓	✓

Errata Number	Rev B (Prototype X-Marked Products)	Rev C
VREF_ERR_04	✓	✓

2 Preprogrammed Software Advisories

Advisories that affect factory-programmed software.

✓ The check mark indicates that the issue is present in the specified revision.

3 Debug Only Advisories

Advisories that affect only debug operation.

✓ The check mark indicates that the issue is present in the specified revision.

4 Fixed by Compiler Advisories

Advisories that are resolved by compiler workaround. Refer to each advisory for the IDE and compiler versions with a workaround.

✓ The check mark indicates that the issue is present in the specified revision.

5 Device Nomenclature

To designate the stages in the product development cycle, TI assigns prefixes to the part numbers of all MSP MCU devices. Each MSP MCU commercial family member has one of two prefixes: MSP or XMS. These prefixes represent evolutionary stages of product development from engineering prototypes (XMS) through fully qualified production devices (MSP).

XMS – Experimental device that is not necessarily representative of the final device's electrical specifications

MSP – Fully qualified production device

Support tool naming prefixes:

X: Development-support product that has not yet completed Texas Instruments internal qualification testing.

null: Fully-qualified development-support product.

XMS devices and X development-support tools are shipped against the following disclaimer:

"Developmental product is intended for internal evaluation purposes."

MSP devices have been characterized fully, and the quality and reliability of the device have been demonstrated fully. TI's standard warranty applies.

Predictions show that prototype devices (XMS) have a greater failure rate than the standard production devices. TI recommends that these devices not be used in any production system because their expected end-use failure rate still is undefined. Only qualified production devices are to be used.

TI device nomenclature also includes a suffix with the device family name. This suffix indicates the temperature range, package type, and distribution format.

5.1 Device Symbolization and Revision Identification

The package diagrams below indicate the package symbolization scheme, and [Table 5-1](#) defines the device revision to version ID mapping.




Figure 5-1. Package Symbolization

Table 5-1. Die Revisions

Revision Letter	Product Development Status	DEVICEID.VERSION
A	Prototype (X-Marked)	0
B	RTM	0

The revision letter indicates the product hardware revision. Advisories in this document are marked as applicable or not applicable for a given device based on the revision letter. This letter maps to an integer stored in the factory constants memory of the device (DEVICEID.VERSION field), which can be used to look up the revision using application software or a connected debug probe.

Note

The DEVICEID.VERSION field is incremented with post RTM (Release to Market) product hardware revisions. Within the same VERSION value, users can identify specific variants by the 'X' character on the silkscreen.

6 Advisory Descriptions

AES_ERR_01 ***AES Module***

Category

Functional

Function

AES Saved Context Ready interrupt is not generating as expected

Description

Saved Context Ready interrupt is not getting generated. The interrupt is generated if an access (read or write) is made to any AES register.

Workaround

Use polling based mechanism to check the status bit for Saved Context Ready in CTRL register instead of interrupt.

BSL_ERR_01 ***BSL Module***

Category

Functional

Function

Invoking the BSL through application software will fail under certain conditions

Description

BSL fails to start through invocation within an application (BSL Software Invoke) due to SRAM error code. After a reset, the device will go back to the application instead of invoking BSL due to the error.

This errata does not apply to BSL invocation through hardware invoke methods

Workaround

For applications needing a software invocation of the BSL, clear the entirety of SRAM with assembly code before resetting device. The MSPM0 bsl_software_invoke example within the MSPM0 SDK v 1.20.01.xx or higher contains an example fix within the "bsl_software_invoke" example.

BSL_ERR_02 ***BSL Module***

Category

Functional

Function

Memory readback always available in the DFU mode

Description

When DFU (USB BSL) mode is invoked, the memory readback command always pass, even if BSL is not unlocked with correct password, or readout feature is disabled in NONMAIN configuration. The memory range check is also bypassed and user can read all memory include Peripheral, MAIN FLASH, NONMAIN FLASH, and SRAM memory.

Workaround

Use secondary BSL to overwrite the security features.

COMP_ERR_06	COMP Module
Category	Functional
Function	COMP output will not become ready or generate interrupts if SYSOSC is disabled before output is ready
Description	Enabling the COMP or changing any of its input configurations (IPSEL/IMSEL) will trigger the OUTRDYIFG bit to be set once the COMPs output is ready. OUTRDYIFG gates all COMP interrupts from firing until the output is ready. The COMP OUTRDYIFG bit requires SYSOSC to be at least 4MHz to become set. If SYSOSC is disabled, OUTRDYIFG will never set and will forever block all COMP interrupts from firing.
Workaround	For COMP to work as expected, SYSOSC must be enabled until the OUTRDYIFG bit is set. Anytime you enable the COMP or configure IPSEL/IMSEL you must wait for OUTRDYIFG bit to be set before entering a LPM that disables SYSOSC or changing the clock to LFCLK. 1. Enable Comparator 2. Configure the IPSEL/IMSEL, as required 3. Wait for OUTRDYIFG interrupt 4. Enter Low Power Mode (LPM) or change clock to LFCLK, if required
CPU_ERR_02	CPU Module
Category	Functional
Function	Limitation of disabling prefetch/cache for CPUSS
Description	CPU prefetch/cache disable will not take effect if there is a pending flash memory access
Workaround	Disable the cache and the prefetcher (order is not mandatory), and then issue a memory access to the shutdown memory (SHUTDNSTORE) in SYSTCL (please check the SHUTDNSTORE registers in the devices TRM for more reference). After the memory access completes, the prefetcher/cache will be disabled. Example: <pre> CPUSS->CTL = (CPUSS_CTL_PREFETCH_DISABLE CPUSS_CTL_ICACHE_DISABLE); //disables instruction caching and pre-fetching DL_SYSCTL_setShutdownStorageByte(DL_SYSCTL_SHUTDOWN_STORAGE_BYTE_X , data) // Save a byte to SHUTDOWN memory </pre>
CPU_ERR_03	CPU Module
Category	Functional

CPU_ERR_03

(continued)

CPU Module

Function

Prefetcher can fetch wrong instructions when transitioning into Low power modes

Description

When transitioning into low power modes and there is a pending prefetch, the prefetcher can erroneously fetch incorrect data (all 0's). When the device wakes up, if the prefetcher and cache do not get overwritten by ISR code, then the main code execution from flash can get corrupted. For example, if the ISR is in the SRAM, then the incorrect data that was prefetched from Flash does not get overwritten. When the ISR returns the corrupted data in the prefetcher can be fetched by the CPU resulting in incorrect instructions. A HW Event wake is another example of a process that will wake the device, but not flush the prefetcher.

Workaround

Disable prefetcher before entering low power modes.

Example:

```
CPUSS->CTL &= 0x6; // disables prefetcher, maintains other settings
SYSCTL.SOCLOCK.SHUTDNSTORE0 // Read from SHUTDOWN Memory
__WFI(); // or __WFE(); this function calls the transition into low power mode
CPUSS->CTL |= 0x1; // enables prefetcher
```

FCC_ERR_01

FCC Module

Category

Functional

Function

FCC behaves incorrectly when BUSCLK is sourced from LFCLK

Description

When BUSCLK is sourced from LFCLK, FCC does not operate as expected. Either the FCC done signal does not assert, or an incorrect FCC value is reported.

Workaround

No workaround

FLASH_ERR_03

FLASH Module

Category

Functional

Function

Flash access with 2 wait states followed by invalid bootcode access will cause next flash access to also throw a violation

Description

Doing a Flash access followed by a access to BOOTCODE when you have 2 wait states will cause the next flash access to also cause a violation.

Workaround

Do not attempt to access boot-code region post-boot phase. Otherwise, there will need to be 4 clock cycles in between the bootcode violation and next correct flash access.

FLASH_ERR_04 *FLASH Module*

Category

Functional

Function

Wrong Address will get reported in the SYSCTL_DEDERRADDR if the error is not in the main flash region.

Description

Workaround

If the return address of the SYSCTL_DEDERRADDR returns a 0x00Cxxxxx, do an OR operation with 0x41000000 to get the proper address for the NONMAIN or Factory region return address. For example, if SYSCTL_DEDERRADDR = 0x00C4013C, the real address would be 0x41C4013C.

If the return address of the SYSCTL_DEDERRADDR returns a 0x00Dxxxxx, do an OR operation with 0x41000000 to get the proper address for the Databank return address. For example, if SYSCTL_DEDERRADDR = 0x00D0012A, the real address would be 0x00D0012A.

FLASH_ERR_05 *FLASH Module*

Category

Functional

Function

DEDERRADDR can have incorrect reset value

Description

The reset value of the SYSCTL->DEDERRADDR can return a 0x00C4013C instead of the correct 0x00000000. The location of the error is in the Factory Trim region and is not indicative of a failure, it can be properly ignored. The reset value tends to change once NONMAIN has been programmed on the device.

Workaround

Accept 0x00C4013C as another reset value, so the default value from boot can be 0x00000000 or 0x00C4013C. The return value is outside of the range of the MAIN flash on the device so there is no potential of this return coming from an actual FLASH DED status.

FLASH_ERR_08 *FLASH Module*

Category

Functional

Function

Hard fault isn't generated for typical invalid memory region

Description

Hard fault isn't generated while trying to access illegal memory address space as shown below: 1. 0x010053FF - 0x20000000 2. 0x40BFFFFFF - 0x41C00000 3. 0x41C007FF - 0x41C40000

Workaround

No

FLASH_ERR_09 *FLASH Module*

Category

Functional

Function

Static write protection on BANK1 is not functional with bank1 erase under specific flash swap policy

Description

If the device flash memory is not the maximum device(e.g. MSPM0L111x family have two different devices as MSPM0L1117 and MSPM0L1116, just MSPM0L1116 has this issue), will get the issue that bank1 be erased unexpectedly under the conditions below:
Failed case 1: Static write protection on BANK1 enabled, flash swap policy disabled, USEUPPER bit of SECCFG_Reg.FLBANKSWP register is 0 or 1, the BANK1 is erased unexpectedly with bank erase command. Failed case 2: Static write protection on BANK1 enabled, flash swap policy enabled, USEUPPER bit of SECCFG_Reg.FLBANKSWP register is 0, the BANK1 is erased unexpectedly with bank erase command.

Workaround

1. Use sector erase instead of bank erase for Bank1. Or 2. Use maximum flash device in the same device family.

GPIO_ERR_05 *GPIO Module*

Category

Functional

Function

Writing to GPIO DOUTTGL registers might get missed when a DMA transfer is ongoing

Description

The GPIO DMAMASK register information is mistakenly applied to a CPU write to the DOUTTGL register when a concurrent DMA transfer is in progress.

Workaround

In the application code, ensure that the GPIO DMAMASK bit is set to 1 for the corresponding bit in the DOUTTGL register, before a CPU write access to the DOUTTGL register is issued. If no DMA transfer to any of the GPIO registers is required, the GPIO DMAMASK can be configured as 0xFFFFFFFF during the IO initialization step. This will solve the conflict of this errata. If the application also requires DMA write transfers to the GPIO registers, it is recommended that the application not use both DMA and CPU to write to the DOUTTGL register of the same GPIO module in the device. If the device has multiple GPIO modules, the DMA and the CPU can simultaneously write to the DOUTTGL register of different GPIO modules (while still requiring that the GPIO DMAMASK be configured for the GPIO module the CPU is writing to).

GPIO_ERR_06 *GPIO Module*

Category

Functional

Function

Writing to GPIO DOUT, DOUTSET and DOUTCLR registers might get missed when a DMA transfer is ongoing

GPIO_ERR_06

(continued)

GPIO Module

Description

The GPIO DOUT, DOUTSET and DOUTCLR registers cannot be accessed by the DMA. Due to mistake in the implementation, the CPU access to the GPIO DOUT, DOUTSET and DOUTCLR will be also be blocked when a concurrent DMA transfer is in progress.

Workaround

In the application code, instead of writing to the DOUT, DOUTSET, and DOUTCLR registers, software should perform equivalent writes to the DOUTTGL register (see workaround GPIO_ERR_05 for restrictions on CPU writes to the DOUTTGL register).

In the pseudo code below, "pins" denotes the bit vector of pins in the GPIO module to be configured.

```
DL_GPIO_setPins(GPIO_Regs* gpio, uint32_t pins)
{
    gpio->DOUTTGL31_0 = ~(gpio->DOUT31_0) & pins;
}

DL_GPIO_clearPins(GPIO_Regs* gpio, uint32_t pins)
{
    gpio->DOUTTGL31_0 = gpio->DOUT31_0 & pins;
}

DL_GPIO_writePins(GPIO_Regs* gpio, uint32_t pins)
{
    gpio->DOUTTGL31_0 = ~(gpio->DOUT31_0) & pins;
    gpio->DOUTTGL31_0 = gpio->DOUT31_0 & (~pins);
}

DL_GPIO_writePinsVal(GPIO_Regs* gpio, uint32_t pinsMask, uint32_t pinsVal)
{
    uint32_t doutVal = gpio->DOUT31_0;
    doutVal &= ~pinsMask;
    doutVal |= (pinsVal & pinsMask);
    gpio->DOUTTGL31_0 = ~(gpio->DOUT31_0) & doutVal;
    gpio->DOUTTGL31_0 = gpio->DOUT31_0 & (~doutVal);
}
```

I2S_ERR_01

I2S Module

Category

Functional

Function

The first TXIFG interrupt does not get fired after I2S/TDM module enabled

Description

Upon I2S/TDM module enable, the first TXIFG interrupt does not get fired.

Workaround

Write a 1 to the INTCTL.INTEVAL bit to generate the initial TXIFG interrupt.

KEYSTORE_ERR_01

KEYSTORE Module

Category

Functional

Function

STATUS.STAT value can be 0 or 1 without key access

Description

STATUS.STAT has a reset value of 1 and turns to 0 under these conditions: 1. After reset, debugger access via the register window returns 0x00. 2. After reset, the first CPU read returns 0x01, while subsequent CPU reads return 0x00. 3) After reset, first reading any other KEYSTORE register and then reading STATUS.STAT return 0x00.

Workaround

STATUS.STAT=0x0 means "No Error" . For checking if a slot is valid or not (Whether key is present), check STATUS.VALID.

PMCU_ERR_14

PMCU Module

Category

Functional

Function

GPIO triggered DMA transfer is got pending until wakeup in low power mode with FCL enabled

Description

When FCL is enabled and in low power mode(STOP2/STANDBY0/STANDBY1), DMA is triggered by event channel from GPIO, this DMA transmission won't start until device is woken up by event or interrupt, and additional power consumption will be seen before waking up.

Workaround

Use GPIO interrupt to start DMA transfer by software, instead of using DMA triggered by GPIO event. And after exit interrupt, re-enter low power mode again.

PMCU_ERR_16

PMCU Module

Category

Functional

Function

Shutdown Current Exceeds Specification at 3.6V Supply Voltage

Description

Under specific corner cases with a VDD supply voltage of 3.6V, the shutdown current exceeds the datasheet specifications. Specifically, at -40C, the shutdown current I_VDD may exceed 200 nA, and the USB shutdown current I_VUSB may exceed 2 uA.

Workaround

No workaround

RST_ERR_01

RST Module

Category

Functional

RST_ERR_01

(continued)

RST Module

Function

Device Remains in Reset When NRST Release Edge Coincides with LFOSCGOOD Rising Edge after A Loss of LFXT or LFCLK_IN

Description

In a specific corner case, if the release edge (low-to-high transition) of the NRST signal coincides with the rising edge of LFOSCGOOD, the device fails to detect the deassertion of NRST and remains in a reset state indefinitely. Conditions that might trigger the issue: When the LFCLK source is switched from LFCLK_IN or LFXT to LFOSC, the LFOSC is re-enabled and LFOSCGOOD status asserts high within 250us (min) to 1.5ms (max) of the re-enable event. If an NRST low pulse is applied such that its release edge (low-to-high transition) aligns with the LFOSCGOOD rising edge within a 50 ns window, the NRST deassertion is not detected and the device remains in reset.

Workaround

Keep the NRST low pulse width higher than 2ms to avoid this issue

RST_ERR_02

RST Module

Category

Functional

Function

Device May Fail to Power Up When NRST deassertion coincides with initial LFOSCGOOD assertion

Description

At power-up event, the internal low-frequency oscillator (LFOSC) is enabled once the internal core voltage (VCORE) reaches a stable level. The LFOSCGOOD signal asserts high within 250us (min) to 1.5ms (max) of VCORE reaching stability. The VBOR+ threshold of VDD can be used as a reference point for when VCORE becomes stable. If the NRST deassertion (low-to-high transition) coincides with the LFOSCGOOD rising edge within a 200ns window, the NRST deassertion is not detected and the device remains in reset, failing to exit the boot phase of the startup sequence. Since the NRST deassertion timing is governed by both the VDD ramp rate and the external resistor and capacitor (RC) network on the NRST circuit, this condition can be triggered in practice - a known susceptible configuration includes a 47 k resistor and 10 nF capacitor on the NRST circuit.

Workaround

Workaround 1: Use a small enough pull-up resistor in the RC filter to ensure the NRST signal rises to 90% of VDD at lesat 50us before the LFOSCGOOD min assertion time (250us), ensuring the NRST deassertion edge is well clear of the LFOSCGOOD assertion window. Note that the required pull-up min resistance depends on the IO drive strength of the external reset controller (if applicable). A known compliant configuration is a 4.7 k resistor with a 10 nF capacitor on the NRST circuit. Workaround2: Employ an external reset controller that holds NRST at a logic low level for a minimum of 2.0 ms from the start of the VDD ramp, ensuring the NRST deassertion occurs after the LFOSCGOOD maximum assertion time (1.5ms).

SPI_ERR_10

SPI Module

Category

Functional

SPI_ERR_10

(continued)

SPI Module

Function

DMA is not sampling the latest SPI trigger count

Description

When SPI is configured to trigger a DMA transfer on a receive timeout (RTOUT) event, if the DMA channel is busy servicing another transfer at the time of the trigger request, any additional bytes received by SPI before the DMA acknowledges the request will not be included in the transfer. The DMA transfers only the number of bytes received when the trigger request was issued, leaving the subsequently received bytes in the RX FIFO unread.

Workaround

Configure DMA_TRIG_RX to use the RX trigger condition in combination with RTOUT. The RX trigger fires when the RX FIFO reaches the configured threshold level, ensuring the full expected number of bytes is present in the FIFO before DMA servicing begins. This guarantees the DMA transfer count is accurate regardless of whether the DMA channel is delayed in acknowledging the request.

SYSCTL_ERR_01 *SYSCTL Module*

Category

Functional

Function

SW-POR functionality is combined with HW-POR

Description

When a user writes to the LFSSRST register with the correct key to generate a software-triggered POR, the RSTCAUSE register will display 0x2 (indicating an NRST-triggered POR) instead of the expected 0x3 (Software-Triggered POR). This occurs because the SW-POR functionality is combined with the HW-POR path.

Workaround

No

SYSCTL_ERR_02 *SYSCTL Module*

Category

Functional

Function

SYSSTATUS.FLASHSEC is non-zero after a BOOTRST

Description

After BOOTRST/ bootcode completion SYSSTATUS.FLASHSEC is non-zero. This the customer will see after bootcode completion.

Workaround

No

SYSCTL_ERR_03 *SYSCTL Module*

Category

Functional

SYSCTL_ERR_03

(continued)

SYSCTL Module**Function***DEDERRADDR persists after a SYSRESET or a write to the SYSSTATUSCLR***Details**

DEDERRADDR persists after either a SYSRESET or a write to the SYSSTATUSCLR register. Its value is overwritten only when a new FLASHDED error occurs. This behavior contradicts the Technical Reference Manual (TRM), which specifies its initial reset value as zero.

Workaround

No workaround

SYSCTL_ERR_04 SYSCTL Module**Category**

Functional

Function

SYSSTATUS.FLASHSEC is not cleared after a SYSRESET

Description

SYSSTATUS.FLASHSEC is not cleared after a SYSRESET and is only cleared by writing to the SYSSTATUSCLR register.

Workaround

Upon returning from SYSRESET, manually clear the FLASHSEC status with
SYSSTATUSCLR = 0xCE000001.

SYSCTL_ERR_05 LFCLK Module**Category**

Functional

Function

LFCLK not working on exit from shutdown

Description

If LFCLK_IN pin is configured as a general input (or) LFCLK_IN function with pull-up, in this configuration, exiting shutdown mode will cause the LFCLK to be stuck.

Workaround

Choose either: 1.Enable pull-down instead of pull-up on this LFCLK_IN I/O 2.Avoid configuring it as an input

SYSCTL_ERR_06 CLK_OUT Module**Category**

Functional

Function

Glitch can occur on External Clock Output (CLK_OUT) when user disables the CLK_OUT while an asynchronous clock was selected as CLK_OUT source

Description

If the clock source for CLK_OUT is asynchronous with the current bus clock (for example, the bus clock is SYSOSC, while the clock source for CLK_OUT is selected as LFCLK),

SYSCTL_ERR_06

(continued)

CLK_OUT Module

then in this case, glitches may appear on the CLK_OUT pin when it is enabled for a period of time and then disabled

Workaround

To avoid the glitch output to external pin, follow below sequence: CLK_OUT enable case: IOMUX enable configuration should be after CLK_OUT enable configuration. CLK_OUT disable case: IOMUX disable configuration should be before CLK_OUT disable configuration.

SYSCTL_ERR_11 ***SYSCTL Module***

Category

Functional

Function

Unexpected BOR reset cycle happens when device in RUN2/SLEEP2 mode with FCL enabled

Description

When FCL is enable and device is running in RUN2/SLEEP2 mode, there is unexpected BOR followed by NMI happens for BOR1/2/3

Workaround

When using BOR1/2/3 monitor, avoid enabling FCL and making device run in RUN2 or SLEEP2 mode.

SYSCTL_ERR_12 ***SYSCTL Module***

Category

Functional

Function

BOR events remain masked post a BOR1/2/3 when device in RUN2/SLEEP2 mode with FCL enabled

Description

When FCL is enabled in RUN2 or SLEEP2 power modes, BOR mask logic does not work as expected, resulting in the failure to detect all subsequent BOR events following the first BOR occurrence. Until software re-enable SYSOSC, BOR MASK is cleared.

Workaround

Workaround 1: Avoid enabling FCL and make device in RUN2/SLEEP2 mode, when BOR1/2/3 detections are needed Workaround 2: Manually clear the BOR mask flag in the BOR/NMI handler after the initial masking period has elapsed Workaround3: Implement a software-based refresh mechanism by periodically toggling Sysosc enable/disable to clear the BOR mask flag

SYSOSC_ERR_01 ***SYSOSC Module***

Category

Functional

Function

MFCLK drift when using SYSOSC FCL together with STOP1 mode

SYSOSC_ERR_01

(continued)

SYSOSC Module

Description

If MFCLK is enabled AND SYSOSC is using the frequency correction loop (FCL) mode AND STOP1 low power operating mode is used, then the MFCLK may drift by two cycles when SYSOSC shifts from 4MHz back to 32MHz (either upon exit from STOP1 to RUN mode or upon an asynchronous fast clock request that forces SYSOSC to 32MHz).

Workaround

Use STOP0 mode instead of STOP1 mode, there is no MFCLK drift when STOP0 mode is used.

OR

Do not use SYSOSC in the FCL mode (leave FCL disabled) when using STOP1.

SYSOSC_ERR_02 SYSOSC Module

Category

Functional

Function

MFCLK does not work when Async clock request is received in an LPM where SYSOSC was disabled in FCL mode

Description

MFCLK will not start to toggle in below scenario:

1. FCL mode is enabled and then MFCLK is enabled
2. Enter a low power mode where SYSOSC is disabled (SLEEP2/STOP2/STANDBY0/STANDBY1).
3. Async request is received from some peripherals which use MFCLK as functional clock. On receiving async request, SYSOSC gets enabled and ulpclk becomes 32MHz. But MFCLK is gated off and it does not toggle at all as the device is still set to the LPM.

Workaround

If SYSOSC is using the FCL mode - Do not enable the MFCLK for a peripheral when you're entering a LPM mode which would typically turn off the SYSOSC.

SYSOSC_ERR_04 SYSOSC Module

Category

Functional

Function

SYSOSC accuracy degrades in FCL ON mode

Description

When using FCL ON mode of the internal oscillator, SYSOSC, accuracy can degrade up to +/-3%. The accuracy degradation is due to a synchronization between the 4MHz FCL sampling clock and noise in the system.

Workaround

If using the SYSPLL FCL ON mode, use a non-4MHz multiple for the SYSPLL frequency, for example: 78MHz or 79MHz

SYSOSC_ERR_04

(continued)

SYSOSC Module

Do not put the SYSPLL at 16, 32, 48, 40, 64, 80MHz etc.

For 78MHz:

Set SYSPLLCFG1.PDIV = 0x3 and SYSPLLCFG1.QDIV to 38

SYSPLL operating frequencies that are not multiples of 4MHz will still align with the FCL sampling clock at least once per microsecond, and more often when the two clocks share a common factor.

SYSOSC_ERR_05

SYSOSC Module

Category

Functional

Function

SYSOSC May Operate Below Base Freq During Async Fast Wakeup from LPM When FCL Is Enabled

Description

When FCL=enabled, SYSOSC may operate up to 10% below its base frequency during low power modes and while there is an active asynchronous fast clock request. This occurs while the device is in low power modes because the FCL = Disabled trim is always applied instead of using FCL= enabled trim even though FCL = enabled. Once the device has woken up, exited LPM, and serviced the request, SYSOSC applies correct trim resumes normal FCL = Enabled operation at its intended target frequency.

Most use cases should have no meaningful impact and can continue to use both FCL and Async fast clock requests as needed. The main applications in which this erratum will have meaningful impact are those where UART is the source of the async fast clock request, as this temporary shift could have impact on the effective baud rate until the device fully wakes.

Workaround

1. Keep FCL = disabled
2. If FCL =Enabled needed, disable Async fast clock requests.

SYSPLL_ERR_01

SYSPLL Module

Category

Functional

Function

SYSPLL Frequency may not lock to correct frequency when enabled.

Description

When setting the SYSPLLEN bit to 1 in SYSCTL HSCLKEN register, the SYSPLL will run the phase locked loop search. The search can potentially fail where the frequency will not be set to the correct value, instead the resultant frequency will be drastically different than the configured frequency.

SYSPLL_ERR_01

(continued)

SYSPLL Module**Workaround****Frequency Verification Process**

Monitor the SYSPLL frequency output using the Frequency Clock Counter (FCC) whenever the SYSPLLEN bit is set to 1. Once the correct frequency is established, it will remain stable until the SYSPLL is disabled and re-enabled (SYSPLLEN bit toggled from 0 to 1). If an incorrect frequency is detected, disable and re-enable the SYSPLL to perform another verification.

Workaround 1: FCC Count Check

Use LFCLK as the FCC trigger source to count the SYSPLL output clock frequency. Execute the FCC and verify the measured value against the configured SYSPLL frequency using LFCLK as reference.

Example calculation:

- SYSPLLCLK0 = 80MHz ; LFCLK = 32.768kHz
- Measured FCC Count = $80,000,000 / 32,768 = 2,441$

FCC Count Tolerance:

The real FCC count will vary depending on the combined clock accuracies (SYSPLLCLK0 and LFCLK). Recommend to add +/- 5~10% to allowed FCC check range.

- FCC count upper limit = $2,441 * 1.05 = 2,563$
- FCC count lower limit = $2,441 * 0.95 = 2,318$

Timing considerations:

- Clock synchronization time: 5-6 LFCLK cycles
- FCC trigger time: 1-32 LFCLK cycles (user-configurable)

Register Configuration:

- FCC Settings: SYSCTL.GENCLKCFG.FCCTRIGSRC = 1;
- SYSCTL.GENCLKCFG.FCCLVLTRIG = 0;
- SYSCTL.GENCLKCFG.FCCTRIGCNT = 0;
- SYSCTL.GENCLKCFG.FCCSELCLK = 4;
- Start FCC: SYSCTL.FCCCMD = 0x0E000001U
- Check FCC Done Status: SYSCTL.CLKSTATUS.FCCDONE
- Read FCC Count: SYSCTL.FCC

Timeout Protection:

Implement a software-based timeout during FCC Done status monitoring to prevent longer wait time under the condition the unlocked SYSPLL frequency is less than FCC trigger clock frequency (LFCLK).

```
fccTimeOutCounter = 0;
while (DL_SYSCTL_isFCCDone() == 0) {
    delay_cycles(977); /* 1x LFCLK cycle = 32MHz/32.768kHz */
    fccTimeOutCounter++;
    if(fccTimeOutCounter > 65) break;
    /* Timeout set to approximately 2ms (user-customizable) */
}
```

FCC Check Restart:

If the FCC measurement falls outside the expected range, disable and re-enable the SYSPLL (set SYSPLLEN to 0, then 1) and repeat the FCC verification.

Workaround 2: FCC Ratio Check

Use LFCLK as the FCC trigger source to count both SYSPLL output and input clock frequency. Execute the FCC and verify the measured ratio of the FCC check value between output and input clock to the expected ratio.

Example calculation:

- SYSPLL = 80MHz ; HFCLK = 40MHz ; LFCLK = 32.768kHz

SYSPLL_ERR_01 (continued)

SYSPLL Module

- Expect clock ratio = 80MHz/40MHz = 2.0000
- Measured FCC count (SYSPLL) = 80,000,000/32,768 = 2,441
- Measured FCC count (HFCLK) = 40,000,000/32,768 = 1,220
- Measured clock ratio = 2,441/1,220 = 2.0008

FCC Ratio Tolerance:

The FCC ratio method eliminates combined clock accuracy errors and depends only on FCC uncertainty (2 counted clock cycles) and calculation rounding error. This allows for much tighter tolerance ranges compared to FCC count check method, for example +/- 0.3%.

Timing considerations:

- Clock synchronization time: 5-6 LFCLK cycles
- FCC trigger time: 1-32 LFCLK cycles (user-configurable)
- Total time per complete FCC ratio check: 2*(sync time + trigger time)

FCC Ratio Check Flow:

1. Configure FCC for SYSPLL output clock (SYSPLL0 or SYSPLL2X)
2. Start FCC and wait for FCC done (Add Timeout Protection, refer to FCC Count Check)
3. Read FCC check count back
4. Configure FCC for SYSPLL input clock (SYSOSC or HFCLK)
5. Start FCC and wait for FCC done (Add Timeout Protection, refer to FCC Count Check)
6. Read FCC check count back
7. Calculate the FCC check ratio and compared to the expected ratio range
8. If the FCC ratio falls outside the expected range, disable and re-enable the SYSPLL (set SYSPLLEN to 0, then 1) and repeat the FCC ratio verification.

TIMER_ERR_04

TIMER Module

Category

Functional

Function

TIMER re-enable may be missed if done close to zero event

Description

When using a TIMER in one shot mode, TIMER re-enable may be missed if done close to zero event. The HW update to the timer enable bit will take a single functional clock cycle. For example, if the timer's clock source is 32.768kHz and clock divider of 3, then it will take ~100us to have the enable bit set to 0 properly.

Workaround

Wait 1 functional clock cycle before re-enabling the timer OR the timer can be disabled first before re-enabling.

Disable the counter with CTRCTL.EN = 0, then re-enable with CTRCTL.EN = 1

TIMER_ERR_06

TIMER Module

Category

Functional

Function

Writing 0 to CLKEN bit does not disable counter

TIMER_ERR_06

(continued)

TIMER Module**Description**

Writing 0 to the Counter Clock Control Register(CCLKCTL) Clock Enable bit(CLKEN) does not stop the timer.

Workaround

Stop the timer by writing 0 to the Counter Control(CTRCTL) Enable(EN) bit.

TIMER_ERR_07***TIMG Module*****Category**

Functional

Function

Initial repeat counter has 1 less period than next repeats

Description

When using the timer repeat counter mode, the first repeat will have 1 less count than the subsequent repeats because the following repeat counters will include the transition between 0 and the load value. For example if the TIMx.RCLD = 0x3 then 3 observable zero events would appear on the first repeat counter and 4 observable zero events would appear on the following repeat counter sequences.

Workaround

Set the initial RCLD value to 1 more than the expected RCLD, then in the ISR for the Repeat Counter Zero Event (REPC), set the RCLD to the intended RCLD value.

For example, if intending to have 4 repeats, set the initial RCLD value to RCLD = 0x5, then in the timer ISR for the REPC interrupt, set RCLD = 0x4. Now all timer repeats will have the same number of zero/load events.

UNICOMMI2CC_ERR_01***UNICOMMI2CC Module*****Category**

Functional

Function

I2C Controller BUSY Status Polling Issue

Description

When initiating an I2C controller transfer by setting the BUSRTRUN/FRAME_START bit, the BUSY status flag requires approximately 2-3 I2C functional clock cycles to assert. If polling the BUSY bit immediately after setting BUSRTRUN/FRAME_START, the status might be checked by the application before it's properly set. This issue is more pronounced with higher CLKDIV values (resulting in slower I2C functional clock) or under higher compiler optimization levels.

Workaround

Add a software delay before polling BUSY status. The recommended delay should be: Software delay = 3 x I2C functional clock = 3 x clock_divider x (CPU_CLK / selected clock source frequency) For example, with a clock_divider of 2, a clock source of 4 MHz(MFCLK), and CPU_CLK of 80 MHz: Software delay = 3 x 2 x (80 MHz / 4 MHz)= 120 CPU cycles

UNICOMMI2CC_E RR_02

UNICOMMI2CC Module

Category

Functional

Function

RXDONE interrupt is triggered twice when I2C controller ACKOEN bit is enabled

Description

When I2C controller CTR.ACKONE bit is enable, software controls the sending of ACK/NACK by writing CTR.ACK bit 0 or 1. This can be done in the RXDONE interrupt before the stop condition. After writing the CTR.ACK bit, there will be valid ACK/NACK signal on I2C bus, and an additional RXDONE interrupt will be triggered in the subsequent I2C stop status.

Workaround

Disable the RXDONE interrupt before writing CTR.ACK bit, and manually enable it before next transmission.

UNICOMMI2CC_E RR_03

UNICOMMI2CC Module

Category

Functional

Function

I2C controller SCL frequency is lower when clock stretching function is enable

Description

- Please do never recommend to use an ETW feature as a workaround. - Please check that the ERRATA proposal does not compromise other existing ERRATAs on this device revision or previous revisions. When clock stretching is enabled, CR.CLKSTRETCH = 1, SCL frequency will be lower than the settings. For example, I2C controller bus speed is set to 400kHz, if clock stretching function is enabled, I2C controller bus clock will be lower than 400kHz, for example, 360kHz or 390kHz. Same phenomenon will be seen on other bus speed, for example, 100kHz or 1Mhz.

Workaround

Not recommended to disable the clock stretching function, because there is no large impact to I2C communication function. After disable the clock stretching function, expected I2C bus clock speed will be seen.

UNICOMMI2CT_ER R_01

UNICOMMI2CT Module

Category

Functional

Function

I2C target will keep in IDLE when CTR is written separately

Description

I2C target will keep in IDLE in below scenario: 1. I2C uses MFCLK as the clock source. 2. CLKDIV=0. 3. Set CTR.START, CTR.STOP or CTR.BLEN bits in first register write. 4. Set CTR.FRM_START in the second register write.

UNICOMMI2CT_ER

R_01 (continued) *UNICOMMI2CT Module*

Workaround

When I2C uses MFCLK as the clock source and CLKDIV=0, suggest to set CTR.START, CTR.STOP, CTR.BLEN or CTR.FRM_START bits in one register write.

UNICOMMI2CT_ER

R_02 *UNICOMMI2CT Module*

Category

Functional

Function

RXFIFO Data Integrity Issue

Description

In UNICOMMI2CT RX mode, RXDONE interrupt flag asserts immediately after last bit of received frame. However, RXFIFO buffer content update exhibits an additional functional clock (I2C functional clock) latency relative to RXDONE assertion. If CPU initiates an RXFIFO read operation before this period, it may access stale FIFO data, causing data integrity violations. This issue is especially problematic when UNICOMMI2CT functional clock is much slower than the CPU clock.

Workaround

Add a fixed delay before reading the RXFIFO to ensure data availability. The recommended delay should be: Software delay = 1 I2C functional clock = 1 clock_divider (CPU_CLK / selected clock source frequency) For example, with clock_divider=2, clock source=4MHz (MFCLK), and CPU_CLK=80MHz: Software delay = 1 2 (80MHz / 4MHz) = 40 CPU cycles

UNICOMMI2CT_ER

R_03 *UNICOMMI2CT Module*

Category

Functional

Function

TSTART Flag Updated ahead of SR.ADDRMATCH update

Description

In UNICOMM_I2CT, interrupt status bit for target START status bit (RIS.TSTART) is set 2-3 I2C functional clock cycles before Address Match Status (SR.ADDRMATCH) bits. If there is CPU access during this time, a stale value may be read. This issue is especially problematic when UNICOMMI2CT functional clock is much slower than the CPU clock.

Workaround

Add a fixed delay before reading the ADDRMATCH. Recommended software delay before reading: Software delay = 3 I2C functional clock = 3 clock_divider (CPU_CLK / selected clock source frequency) For example, with clock_divider=2, clock source=4MHz (MFCLK), and CPU_CLK=80MHz: Software delay = 3 2 (80MHz / 4MHz) = 120 CPU cycles

UNICOMMSPI_ER

R_01 *UNICOMMSPI Module*

Category

Functional

UNICOMMSPI_ER

R_01 (continued)

UNICOMMSPI Module

Function

SPI underflow event may not generate if read/write to TXFIFO happen at the same time

Description

When operating in SPI peripheral mode, a race condition exists that can cause status flag inaccuracies. This issue occurs under the following specific conditions: 1. The transmit FIFO becomes empty 2. The SPI peripheral receives a request to send data (typically from an external Controller) 3. The CPU/DMA attempts to write new data to the transmit buffer 4. This CPU/DMA write operation occurs simultaneously with a new transmit request from the Controller Under these timing-sensitive circumstances, the status flags (such as FIFO empty/underflow flags) may report incorrect states. This can lead to data transmission errors or missed interrupts. This issue may cause: Incorrect status flag readings Potential data transmission errors Unreliable interrupt generation

Workaround

To mitigate this issue: 1. Carefully manage data rate between CPU/DMA & SPI Peripheral 2. For critical applications, consider using a higher priority for DMA transfers to SPI transmit buffer.

UNICOMMSPI_ER

R_02

UNICOMMSPI Module

Category

Functional

Function

Controller Side Busy status read incorrectly

Description

SPI busy status doesn't depend on the TXFIFO's data elements, so essentially once we load the SPI TXFIFO with some data, the busy bit will not go high instantly in case the CLKSEL is a slower clock (LFCLK for instance) or CLKDIV > /1. This leads to incorrect status being read during the time between loading TXFIFO data and until the communication actually starts since the SPI source clock is slower.

Workaround

Can introduce a check for TXFIFO empty STATUS bit when writing application code.

UNICOMMSPI_ER

R_03

UNICOMMSPI Module

Category

Functional

Function

RTOUT won't be set at second time when CPU is used to clear RXFIFO

Description

After SPI communication is completed with rxtimeout enabled and then RTOUT is set, if use CPU to read out the RXFIFO data and read IIDX to clear the interrupt but don't do any reset or disable the IP, the RTOUT interrupt won't be set when you do the same transmission at the second time even though rxtimeout counter is "0" and RXFIFO is not empty.

UNICOMMSPI_ER**R_03** (continued)***UNICOMMSPI Module***

Workaround

Use DMA to read out the RXFIFO data instead of using CPU directly .Or reset the UNICOMM SPI after reading out the RXFIFO data using CPU directly.

UNICOMMSPI_ER**R_04*****UNICOMMSPI Module***

Category

Functional

Function

RX stored data is incorrect when do re-transfer after last one transfer with DSS mismatch

Description

When sending data with different data packet size setting (DSS) on controller & peripheral side and after that doing RXCLR to clear the FIFO, again sending data with proper data package size but still older data is coming into RXFIFO when first SCLK pulse comes.

Workaround

Please make sure the data package size setting (DSS) on controller side and peripheral side is same.

UNICOMMUART_E**RR_01*****UNICOMMUART Module***

Category

Functional

Function

Data integrity issues in case glitches are introduced in IrDA mode

Description

UNICOMM-UART supports IrDA but has limitations in noisy environments. Due to the lack of a glitch filter, data integrity issues can occur in IrDA mode when glitches appear on the data line. Since IrDA relies on edge detection logic, these glitches are misinterpreted as valid pulses, leading to unexpected data in the FIFO and issues with LTOUT computation.

Workaround

No

UNICOMMUART_E**RR_02*****UNICOMMUART Module***

Category

Functional

Function

IDLE period detection issue with glitch in IDLELINE mode

Description

A glitch during the idle period can corrupt the receiver's idle detection, causing the Rx side to drop the subsequent address byte. Crucially, this failure mode is timing-dependent: only glitches inserted at a specific time relative to the idle period trigger the issue. Not every glitch within the idle period causes corruption.

UNICOMMUART_E

RR_02 (continued) *UNICOMMUART Module*

Workaround No

UNICOMMUART_E

RR_03 *UNICOMMUART Module*

Category Functional

Function Data Integrity issues with glitch in Manchester mode

Description Glitches in the Manchester-encoded data stream corrupt the signal's precise edge timing, leading to erroneous received data and data integrity issues.

Workaround No

UNICOMMUART_E

RR_04 *UNICOMMUART Module*

Category Functional

Function Data will be missed with glitches during break field and/or sync field in LIN Mode

Description Break Field Scenario (High-Pulse Glitch): During the Break Field period, a negative edge will reset the counter to zero, cause break field detection failure and result in data loss. Sync Field Scenario: A glitch during Sync Field will trigger false LINC0/LINC1 interrupts, reset the counter on Rx-line negative edges, cause sync field validation failure and result in data loss.

Workaround No

UNICOMMUART_E

RR_05 *UNICOMMUART Module*

Category Functional

Function Issue due to UART Glitch Filter not being present

Description 1.IRDA Mode Data Integrity: Due to the lack of a glitch filter, data integrity issues can occur in IrDA mode when glitches appear on the data line. Since IrDA relies on edge detection logic, these glitches are misinterpreted as valid pulses. 2.Ideline detection: During IDLELINE detection, a signal glitch can disrupt the detection process by resetting the internal idle line counter to zero. This interference prevents the IDLELINE status flag from being properly set, causing the module to fail to recognize a valid idle condition on the communication line. However, if the idle line condition persists without additional

UNICOMMUART_E**RR_05 (continued) UNICOMMUART Module**

glitches after this disruption, the detection mechanism will eventually recover and properly detect the idle state. 3. Manchester Mode Data Integrity: When signal glitches occur during the data sampling period of Manchester-encoded transmissions, the receiver captures incorrect data, leading to misinterpreted bits. These sampling errors result in corrupted data values being stored in the receive buffer, causing data integrity failures in the received message. Glitches occurring outside the sampling window typically do not affect data interpretation. 4. LIN mode sensitivity around BREAK / SYNC field: a. BREAK Field: During LIN communication, if signal glitches occur specifically during clock sampling periods of the BREAK FIELD, the detection mechanism may prematurely terminate. However, the system demonstrates resilience - if the BREAK FIELD condition continues without additional glitches after the disruption, the detection logic will recover and successfully identify the BREAK FIELD. b. SYNC Field: The system exhibits comparable vulnerability during SYNC field calibration, where glitches can interfere with both negative and positive edge (RXNE & RXPE) detection. 5. LTOUT/RTOUT Detection issue with glitches: When signal glitches occur during idle line detection conditions, they temporarily disrupt the LTOUT/RTOUT timing calculations, and the timeout counters are cleared back to 0. If the line remains free from additional glitches after the disruption, LTOUT/RTOUT conditions are detected after the configured time-period.

Workaround

No workaround is available.

UNICOMMUART_E**RR_06 UNICOMMUART Module**

Category

Functional

Function

RTOUT/LTOUT computation issues due to STOP bit handling

Description

On the receiver side, the function state machine transitions from STOP bit to IDLE at the middle of the STOP bit. This causes the receive timeout (RTOUT) & line timeout (LTOUT) counter to start counting at the middle of the STOP bit and not at its end. Leading to RTOUT/LTOUT being triggered half a baud-period early. This is especially pronounced for low-baud rates with higher UART functional clock frequency.

Workaround

Add compensation with a half stop bit period to the RTOUT counter.

UNICOMMUART_E**RR_07 UNICOMMUART Module**

Category

Functional

Function

RTS line does not go HIGH if UART is disabled in RS-232 mode

Description

When UART is disabled, the RTS line fails to return to its idle state (HIGH), remaining stuck at LOW.

UNICOMMUART_E

RR_07 (continued) *UNICOMMUART Module*

Workaround Use software to enable the internal pull-up resistor and set the RTS line IO to Hiz mode.

UNICOMMUART_E

RR_08 *UNICOMMUART Module*

Category Functional

Function Continuous LTOUT interrupts

Description After a line timeout (LTOUT) interrupt occurs, the counter restarts and continues counting, generating LTOUT interrupts at every timeout expiry interval. This issue also applies to the RTOUT event.

Workaround Disable LTOUT detection in the LTOUT ISR. Re-enable after receiving a new character.

UNICOMMUART_E

RR_09 *UNICOMMUART Module*

Category Functional

Function ISO-7816 Smartcard Mode baud rate limitation

Description To achieve a 9600 baud rate in ISO-7816 Smartcard Mode, a UARTCLK frequency exceeding 57 MHz is required due to the following constraints: 1. The ISO-7816 standard requires 372 clock cycles per bit 2. In MSPM0 ISO-7816 mode, the oversampling rate (OVS) is fixed at 16x in the UART peripheral Minimum UARTCLK calculation: Required UARTCLK = $9600 \times 372 \times 16 = 57.139 \text{ MHz}$

Workaround UART with lower input frequency will not be able to support SMARTCARD mode.

UNICOMMUART_E

RR_10 *UNICOMMUART Module*

Category Functional

Function LIN Registers CLKDIV Restriction

Description When CLKDIV value is other than 0, writing into LINC0/1 will not have any effect.

Workaround To properly configure LIN registers: 1. First set CLKDIV to '0' 2. Update the LINC0/1 register configurations with desired values 3. Restore CLKDIV to its intended operating value

UNICOMMUART_E
RR_11 *UNICOMMUART Module*

Category

Functional

Function

BUSY Bit Remains Set After UART Disabled

Description

The STAT.BUSY bit remains high (asserted) when there is data in the FIFO even though UNICOMMUART is disabled.

Workaround

Set IFLS.TXCLR bit to clear TXFIFO contents prior to disabling the UNICOMMUART.

UNICOMMUART_E
RR_12 *UNICOMMUART Module*

Category

Functional

Function

CTL0.TXE bit setting to 0 in middle of frame makes current transmission error

Description

Start transmitting packet and then in middle of transfer, set the CTL0.TXE bit to 0, the current packet won't complete and the TX line will be pulled low, which shows the busy behavior as BUSY. The TX line will be released only when CTL0.TXE = 1, and till then BUSY remains 1.

Workaround

User must poll for BUSY STATUS to go low and CTL0.TXE = 0, so as to avoid this issue.

UNICOMMUART_E
RR_13 *UNICOMMUART Module*

Category

Functional

Function

RTOUT interrupt coming 1 fclk cycle earlier

Description

RTOUT (Receive timeout) interrupt coming 1 fclk cycle earlier from the exact time which it should come for.

Workaround

The way user can take care of this is to expect the RTOUT interrupt to come one fclk cycle earlier.

UNICOMMUART_E
RR_14 *UNICOMMUART Module*

Category

Functional

UNICOMMUART_E

RR_14 (continued) *UNICOMMUART Module*

Function	CTS interrupt gets toggled on both falling and rising edges of CTS line
Description	CTS interrupt gets toggled on both RISE edge as well as FALL edge of CTS line. Ideally, it should just toggle on the FALL edge of CTS line.
Workaround	Instead of RIS bit, user can monitor STAT.CTS bit's toggle to 1, since this toggling of STAT.CTS = 1 indicates that falling of CTS line has been encountered.

UNICOMMUART_E

RR_15 *UNICOMMUART Module*

Category	Functional
Function	LCRH.SENDIDLE access missed in between fclk and new IDLELINE frame not produced
Description	If toggle LCRH.SENDIDLE from 0 to 1 and then back from 1 to 0, or toggle from 1 to 0 and then back from 0 to 1 in between two fclk edges, the toggle will be missed and no new IDLELINE frame is sent.
Workaround	After toggling LCRH.SENDIDLE, don't put it back immediately, please keep more than one fclk period, because LCRH.SENDIDLE is sampled on fclk.

USB_ERR_01 *USB Module*

Category	Functional
Function	Clearing CLKEN Bit Before FLEN Bit Does Not Disable USBFLL
Description	When the CLKEN bit is cleared while the FLEN bit remains set, the USBFLL clock retains its locked state and is not disabled as expected.
Workaround	Clear the FLEN bit prior to clearing the CLKEN bit to properly disable the USBFLL clock.

USB_ERR_02 *USB Module*

Category	Functional
Function	DMADONE and DMAPREIRQ bits are swapped in IMASK, RIS and MIS registers
Description	The IMASK, RIS and MIS registers contain a bit assignment error where the DMADONE and DMAPRERD bit positions are incorrectly swapped: - DMAPREIRQ bits (19:12) indicate the corresponding DMADONE interrupt status (contrary to their intended function)

USB_ERR_02

(continued)

USB Module

- DMADONE bits (11:4) indicate the corresponding DMA-pre interrupt status (contrary to their intended function) This bit swapping also affects the IIDX register read back value. For examples: - BIT4 is designed for DMADONEARX, while it actually indicates the DMAPREARX (BIT12) - BIT5 is designed for DMADONEATX, while it actually indicates the DMAPREATX (BIT13) - BIT11 is designed for DMADONEDTX, while it actually indicates the DMAPREDTX (BIT19)

Workaround

No workaround.

USB_ERR_03**USB Module****Category**

Functional

Function

USB FLL frequency lock time is increased when set SOF as FLL reference clock

Description

When SOF (Start of Frame) is used as the USBFLL reference, a corner case exists where the USBFLL may require extended time to lock the correct frequency. Test results indicate the lock time can up to ~30ms.

Workaround

1. Use LXFT instead of SOF as the USB FLL reference clock source (Set USBFLLCTL.REFSEL as 1h) 2. Select SYSPLL as USB clock source (Set GENCLKCFG.USBCLKSRC as 1h)

USB_ERR_04**USB Module****Category**

Functional

Function

Endpoint interrupts might get missed, when multiple endpoints are configured

Description

When data is received or transmitted on a configured endpoint, the corresponding EP interrupt is recorded in the INTRTX or INTRRX register. Any new event on these registers will trigger an interrupt event to the CPU. The ISR handler need to read the INTRTX and INTRRX to identify the origin of the interrupt and to clear the interrupt register. The automatic clear operation of the interrupt register takes three CPU clock cycles. In a system with several configured endpoints it can happen that a new EP interrupt comes in while the automatic clear process is still in progress. As a result the INTRTX or INTRRX register will stay asserted without the recognition of a new interrupt event generation to the CPU.

Workaround

When reading the INTRTX or INTRRX register, read the INTRTX or INTRTX several time to assure the interrupt register is really cleared. This way it is assured a new interrupt is recognized as a new interrupt event and properly reported to the CPU.

Below is an example of code implementation:

USB_ERR_04

(continued)

USB Module

```
uint_fast8_t intr = 0; /* interrupt status */
uint_fast8_t intr_reg = 0; /* temporary interrupt register */
intr_reg = musb_regs->intr_tx; /* reading intr_tx clears register, but new one might come in */
while (intr_reg) { /* read multiple times till intr_tx is cleared */
    intr |= intr_reg; intr_reg = musb_regs->intr_tx;
}
intr &= musb_regs->intr_txen; /* clear disabled interrupts */
/* process EP0 */
if (intr & TU_BIT(0)) {
    process_ep0(rhport); intr &= ~TU_BIT(0);
}
/* process EPn */
while (intr) {
    unsigned const num = __builtin_ctz(intr);
    process_edpt_n(rhport, tu_edpt_addr(num, TUSB_DIR_IN));
    intr &= ~TU_BIT(num);
}
```

VREF_ERR_04

VREF Module

Category

Functional

Function

VREF can't be used by ADC when Comparator is in sampled (ultra-low-power) mode

Description

The 2 use-cases below don't allow the ADC to use VREF if the comparator (COMP) is in sampled (ultra-low-power) mode.

Case 1:

Configuration : The ADC is configured to use internal VREF as its reference, while the COMP uses either VDDA or external reference with sample-and-hold mode enabled

Issue : The internal VREF module enters sample-and-hold mode when triggered by the COMP's VDDA/External reference request, making VREF unavailable to the ADC.

Case 2:

Configuration : Both the ADC and COMP are configured to use internal VREF as their reference, with the COMP operating in sampled mode.

Issue : The VREF module enters sample-and-hold mode due to the COMP's sample-and-hold request, preventing ADC access to VREF.

Workaround

Before enabling the ADC sampling, make sure the COMP is not configured in sampled (ultra-low-power) mode.

Example:

```
COMP.CTL2.REFMODE = 0;
```

7 Trademarks

All trademarks are the property of their respective owners.

8 Revision History

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

Changes from November 30, 2025 to September 31, 2026 (from Revision * (November 2025) to Revision A (September 2026))

	Page
• Initial Release.....	1
• BSL_ERR_01 Advisory was added.....	5
• BSL_ERR_02 Advisory was added.....	5
• COMP_ERR_06 Advisory was added.....	6
• CPU_ERR_02 Function was updated.....	6
• CPU_ERR_02 Description was updated.....	6
• CPU_ERR_02 Workaround was updated.....	6
• CPU_ERR_03 Workaround was updated.....	6
• FCC_ERR_01 Advisory was added.....	7
• FLASH_ERR_09 Advisory was added.....	9
• GPIO_ERR_06 Description was updated.....	9
• GPIO_ERR_06 Workaround was updated.....	9
• I2S_ERR_01 Advisory was added.....	10
• PMCU_ERR_14 Advisory was added.....	11
• PMCU_ERR_16 Advisory was added.....	11
• RST_ERR_01 Workaround was updated.....	11
• RST_ERR_02 Advisory was added.....	12
• SPI_ERR_10 Advisory was added.....	12
• SYSCTL_ERR_04 Workaround was updated.....	14
• SYSCTL_ERR_05 Advisory was added.....	14
• SYSCTL_ERR_06 Advisory was added.....	14
• SYSCTL_ERR_11 Advisory was added.....	15
• SYSCTL_ERR_12 Advisory was added.....	15
• SYSOSC_ERR_04 Advisory was added.....	16
• SYSOSC_ERR_05 Advisory was added.....	17
• SYSPLL_ERR_01 Workaround was updated.....	17
• TIMER_ERR_06 Module was updated.....	19
• UNICOMMI2CC_ERR_01 Function was updated.....	20
• UNICOMMI2CC_ERR_01 Description was updated.....	20
• UNICOMMI2CC_ERR_01 Workaround was updated.....	20
• UNICOMMI2CC_ERR_02 Advisory was added.....	21
• UNICOMMI2CC_ERR_03 Advisory was added.....	21
• UNICOMMI2CT_ERR_02 Function was updated.....	22
• UNICOMMI2CT_ERR_02 Description was updated.....	22
• UNICOMMI2CT_ERR_02 Workaround was updated.....	22
• UNICOMMI2CT_ERR_03 Function was updated.....	22
• UNICOMMI2CT_ERR_03 Description was updated.....	22
• UNICOMMI2CT_ERR_03 Workaround was updated.....	22
• UNICOMMSPI_ERR_01 Description was updated.....	22
• UNICOMMSPI_ERR_01 Workaround was updated.....	22
• UNICOMMSPI_ERR_02 Advisory was added.....	23
• UNICOMMSPI_ERR_03 Advisory was added.....	23
• UNICOMMSPI_ERR_04 Advisory was added.....	24
• UNICOMMUART_ERR_05 Function was updated.....	25
• UNICOMMUART_ERR_05 Workaround was updated.....	25
• UNICOMMUART_ERR_05 Description was updated.....	25
• UNICOMMUART_ERR_06 Function was updated.....	26
• UNICOMMUART_ERR_06 Description was updated.....	26

• UNICOMMUART_ERR_06 Workaround was updated.....	26
• UNICOMMUART_ERR_08 Function was updated.....	27
• UNICOMMUART_ERR_08 Description was updated.....	27
• UNICOMMUART_ERR_08 Workaround was updated.....	27
• UNICOMMUART_ERR_09 Function was updated.....	27
• UNICOMMUART_ERR_09 Description was updated.....	27
• UNICOMMUART_ERR_09 Workaround was updated.....	27
• UNICOMMUART_ERR_10 Function was updated.....	27
• UNICOMMUART_ERR_10 Description was updated.....	27
• UNICOMMUART_ERR_10 Workaround was updated.....	27
• UNICOMMUART_ERR_11 Function was updated.....	28
• UNICOMMUART_ERR_11 Description was updated.....	28
• UNICOMMUART_ERR_11 Workaround was updated.....	28
• UNICOMMUART_ERR_12 Advisory was added.....	28
• UNICOMMUART_ERR_13 Advisory was added.....	28
• UNICOMMUART_ERR_14 Advisory was added.....	28
• UNICOMMUART_ERR_15 Advisory was added.....	29
• USB_ERR_01 Advisory was added.....	29
• USB_ERR_02 Advisory was added.....	29
• USB_ERR_03 Advisory was added.....	30
• USB_ERR_04 Advisory was added.....	30
• VREF_ERR_04 Advisory was added.....	31

IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATASHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, regulatory or other requirements.

These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you fully indemnify TI and its representatives against any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to [TI's Terms of Sale](#), [TI's General Quality Guidelines](#), or other applicable terms available either on [ti.com](#) or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products. Unless TI explicitly designates a product as custom or customer-specified, TI products are standard, catalog, general purpose devices.

TI objects to and rejects any additional or different terms you may propose.

Copyright © 2026, Texas Instruments Incorporated

Last updated 10/2025