ZZ1 ■ These assemblies are ESD sensitive, ESD precautions shall be observed.
ZZ2 ■ These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.
ZZ3 ■ These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.
ASSEMBLY VARIANT: 002

PCB VIEWED FROM TOP SIDE	BOARD #: MCU119	REV: B	SUN REV: Not in version control
M5 Assembly Top	TID #: N/A		
PLOT NAME = Top Assembly Drawing	GENERATED : 11/9/2026 2:40:14 PM		TEXAS INSTRUMENTS



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.
ASSEMBLY VARIANT: 002

PCB VIEWED FROM BOTTOM SIDE	BOARD #: MCU119	REV: B	SUN REV: Not in version control
	TID #: N/A		Bottom Assembly Drawing
PLOT NAME = Bottom Assembly Drawing	GENERATED : 11/9/2026 2:40:16 PM		TEXAS INSTRUMENTS