

ZZ2 ■ These assemblies are ESD sensitive, ESD precautions shall be observed.
ZZ3 ■ These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.
ZZ4 ■ These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.
ZZ1 ■ Install label in silkscreened box after final wash. Text shall be 8 pt font. Text shall be per the Label Table in the PDF schematic.



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.

ASSEMBLY VARIANT: 001_100baseT1

PCB VIEWED FROM TOP SIDE	BOARD #: TIDA-011055	REV: E1	SUN REV: Not in version control
	TID #: TIDA-011055		
PLOT NAME = Top Assembly Drawing	GENERATED : 10/19/2026 7:07:03 PM		TEXAS INSTRUMENTS



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.

ASSEMBLY VARIANT: 001_100baseTI

PCB VIEWED FROM BOTTOM SIDE	BOARD #: TIDA-011055	REV: E1	SUN REV: Not in version control
	TID #: TIDA-011055		
PLOT NAME = Bottom Assembly Drawing	GENERATED : 10/19/2026 7:07:03 PM		TEXAS INSTRUMENTS