

Resetting Non-FIFO Variations of the 10-Bit THS10064

Tom Hendrick

Data Acquisition Products—Applications

ABSTRACT

The THS1007 and THS1009 are non-FIFO variations of the THS10064. They require some special procedures for properly resetting and configuring the device. This application brief explains the necessary steps required to get reliable data from these 10-bit, two and four channel simultaneous sampling data converters.

Contents

1	Introduction	1
2	Resetting the SYNC Generator	2
3	Reading Data	3

List of Figures

1	THS1007 Configuration Flow	. 2	2
2	SYNC Pulse in 2, 3, and 4 Channel Modes	. 3	3

1 Introduction

The THS1007 and THS1009 are counterparts to the THS10064, 4 channels, 10-bit, simultaneous sampling, 6 MSPS analog-to-digital converter. Aside from sampling rate and channel count, the major difference in these parts is that the FIFO has been removed.

This application brief explains the necessary steps required to configure the device, as well as read reliable/consistent data.



2 Resetting the SYNC Generator

Bit 1 of configuration register 1 (CR1), must be considered the SYNC generator reset bit (SRST). This is similar to the THS10064 in that the THS10064 uses this bit to reset the FIFO to a known starting position. Similar results are possible by writing a 1 to CR1, bit 1, during the reset/configuration sequence of the THS1007 and THS1009.

This flow chart shows the initialization sequence of the THS1007. After power up, it is necessary to perform a device reset by writing hex values 0x401 and 0x400 to the device.

If the default configuration values are desired, there is no need to perform any additional writes to the device. The default value for configuration register 0 (CR0) is 0x020. The default value for CR1 is 0x030.

Because the default configuration values select single channel operation, the SYNC pulse is disabled, and there is no need to reset the SYNC generator.

If multiple channel operation is desired, it is necessary to set the SRST bit as part of the user configuration write to CR1 (CR1 bit 1 = 1). It is not necessary to clear the SRST bit once it has been set.




Figure 1. THS1007 Configuration Flow

3 Reading Data

Proper data readings depend on the proper application of the read signal. As with the THS10064, the THS1007 and THS1009 can be configured with independent, active low, read and write strobes. Active low CS0 and active high CS1 provide chip selection to the device and can be tied to static levels if desired.

With the non-FIFO devices, it is necessary to issue a read strobe after each CONV_CLK. It is not appropriate to consider the SYNC pulse as an interrupt source to the controller. The SYNC pulse is merely an indiction that data currently available is the data acquired from channel one.

The read SYNC pulse is not available when the device is configured for single channel operation. The SYNC pulse is only active when two or more channels are selected for conversion during the initialization sequence.

Data setup times are listed in the data sheets as t_{su} (CONV_CLK_READL). The read strobe must be applied after this setup time but before the subsequent falling CONV_CLK edge. Failure to read the data bus within each conversion cycle, or multiple reads during the same conversion cycle, can cause the non-FIFO THS1007 and THS1009 SYNC pulse to behave erratically. Resetting BIT 1 of CR1 clears erratic SYNC pulse behavior.




Figure 2. SYNC Pulse in 2, 3, and 4 Channel Modes

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third–party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

Mailing Address:

Texas Instruments Post Office Box 655303 Dallas, Texas 75265

Copyright © 2002, Texas Instruments Incorporated