

ZZ1
Label Assembly Note
 This Assembly Note is for PCB labels only

ZZ2

Assembly Note

These assemblies are ESD sensitive, ESD precautions shall be observed.

ZZ3


Assembly Note

These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.

ZZ4

Assembly Note

These assemblies must comply with workmanship standards IPC-A-610 Class 2., unless otherwise specified.

Number: PMP9643		Rev: E2	Designed for: Public Release	Mod. Date: 24/03/2014	 TEXAS INSTRUMENTS http://www.ti.com © Texas Instruments 2014
Project Title: UCC28630			Sheet Title:		
SVN Rev: Not in version control			Assembly Variant: 001	Sheet: 2 of 2	
Drawn By:			File: PMP9643HW_SchDoc	Size: B	
Engineer: Billy Long			Contact: http://www.ti.com/support		

Texas Instruments and/or its licensors do not warrant the accuracy or completeness of this specification or any information contained therein. Texas Instruments and/or its licensors do not warrant that this design will meet the specifications, will be suitable for your application or fit for any particular purpose, or will operate in an implementation. Texas Instruments and/or its licensors do not warrant that the design is production worthy. You should completely validate and test your design implementation to confirm the system functionality for your