



- ZZ2 ■ These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.
- ZZ1 ■ These assemblies are ESD sensitive, ESD precautions shall be observed.
- ZZ3 ■ These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.
- ZZ4 ■ Install label in silkscreened box after final wash. Text shall be 8 pt font. Text shall be per the Label Table in the PDF schematic.

COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.

ASSEMBLY VARIANT: 004

PCB VIEWED FROM TOP SIDE	BOARD #:	MDO69	REV:	C	SUN REV:	Not in version control
	TID #:	N/A				
PLOT NAME = Top Assembly Drawing	GENERATED :	2/28/2024	4:56:26 PM			TEXAS INSTRUMENTS



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.  
ASSEMBLY VARIANT: 004

PCB VIEWED FROM BOTTOM SIDE	BOARD #: MDO69	REV: C	SUN REV: Not in version control
	TID #: N/A		
PLOT NAME = Bottom Assembly Drawing	GENERATED : 2/28/2024 4:56:27 PM		TEXAS INSTRUMENTS