TI-RSLKMAX

Texas Instruments Robotics System Learning Kit





Module 16

Activity: Tachometer



Question 1

If Timer_A is clocked at 12 MHz, with a prescale of 32, what is the slowest period that can be measured?

Question 2

Read the MSP432 data sheet on the Timer_A. Assume two or more input capture pins are armed to create interrupts on TA3_N_IRQhandler. Explain how the TA3IV register is used to determine which pin caused the interrupt.

Question 3

Read the MSP432 data sheet on the Timer_A. First, explain how to configure the ACLK to oscillate at 32.768 kHz. Second, explain how to configure the input capture to use the ACLK with prescale equal to 1. At these settings what will be the range, resolution and precision of the input capture measurement?

Question 4

Explain how to measure pulse width, PW, using input capture?



Question 5

Explain how to measure duty cycle using input capture?

Duty cycle = H/(H+L)



Question 6

Assume an input is connected to P7.3. Write software that measures pulse width (rising to falling edges) using interrupts.



Question 7

Read the MSP432 data sheet for the **Timer_A** module. Where does the clock TAxCLK come from? Think of applications that might use this clock to run input capture mode?

ti.com/rslk



IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATASHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, or other requirements. These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to TI's Terms of Sale (www.ti.com/legal/termsofsale.html) or other applicable terms available either on ti.com or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products.

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265 Copyright © 2019, Texas Instruments Incorporated