


Initial Hardware Setup and Connections


9V
GND

USB
Cable




Connect USB DIG to INA219EVM

(Squeeze together on both sides of DSUB Connectors)



Connect Cables

Connect DC
Wall-wart to
J5 or 9V
power supply
to T3





Connect Cables

Turn on the PC Sound.


Connect USB Connector J1 to PC USB Port.

The first time a USB DIG Board is plugged into your computer you may get a message (as shown below).





Positive Differential Input Voltage



Negative Differential Input Voltage

